



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|------|---------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS3/CTI21011458/Vuy3 | |
| | | | Date: 09/11/2021 | |
| | | | Code: CTI | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | GBB 9452K | | Veh. Inspected | SMK 3171H |
| Policy No. | DMCVSNA00059562100 | | Coverage (\$) | 0.00 |
| Claim No. | SNM21D206423/C02/GBB9452 K/TANKL | | Excess (\$) | 0.00 |
| Assign From | TAN KAH LEONG | | Assign Date | 09/11/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | | c.c | 0 |
| Engine No. | HIDDEN | | Year of Reg. | |
| Chassis No. | | | Colour | |
| Odometer | - | | Steering | |
| Brakes | | | Modification | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 05/11/2021 | | Inspection Date | 10/11/2021 |
| Survey held at | SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | |