

Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 4179

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBC1879K

Accident Date : 9/11/2021

Location : BKE TOWARDS KJE

TP AIG

Jaslin

V SKYBAM 2000021323

Model:

NISSAN NV200

27/7/2011

3P:

SJS3921E (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$	
1	1 pc	Rear bumper <i>dent</i>			695.90	✓
2	2pcs	Rear bumper o/s & n/s retainer <i>new</i>			86.60	✓
3	10 pcs	Rear bumper clips <i>new</i>		30.00	✓	
4	1 pc	Rear bumper sponge <i>caulking</i>			90.20	✓
5	2ps	Rear bumper o/s & n/s reflector <i>new</i>			103.40	+
6	2pcs	Rear o/s & n/s tail lamp <i>new</i>			731.20	+
7	2pcs	Rear o/s & n/s tail lamp inner seal <i>new</i>		20.00	+	
8	1 pc	Rear main frame weather strip <i>new</i>			210.00	✓
9	1 pc	Rear o/s tail gate <i>dent</i>			1,057.00	✓
10	1 pc	Rear o/s tail gate weatherstrip <i>new</i>			215.00	+
11	1 pc	Rear o/s tail gate lock <i>new</i>			215.50	+
12	1 pc	Rear o/s tail gate lock catch <i>new</i>			63.60	+
13	2pcs	Rear o/s tailgate hinges <i>new</i>			120.00	+
14	1 pc	Rear o/s tailgate striker <i>new</i>			80.00	+
15	1 pc	Rear o/s windscreen moulding <i>new</i>		130.00	✓	
16	1 pc	Rear o/s windscreen sealant <i>new</i>		80.00	✓	
17	1 pc	Rear n/s tail gate <i>dent</i>		60	1,409.20	✓
18	1 pc	Rear n/s tail gate protector strip <i>new</i>		80.00	40	
19	1 pc	Rear n/s tail gate inner board <i>new</i>			180.00	+
20	12pcs	Rear n/s tail gate inner board clips <i>new</i>		36.00	+	
21	1 pc	Rear n/s tail gate moulding <i>new</i>			143.00	+
22	4 pcs	Rear n/s tail gate moulding clips <i>new</i>		16.00	+	
23	1 pc	Rear n/s tail gate lock <i>dent</i>			215.50	✓
24	1 pc	Rear n/s tail gate lock catch <i>new</i>			63.60	+
25	1 pc	Rear n/s tailgate lock (upper) <i>new</i>			215.50	+
26	1 pc	Rear n/s tailgate lock catch (upper) <i>new</i>			63.60	+
27	2pcs	Rear n/s tailgate hinges <i>new</i>			120.00	+
28	1 pc	Rear n/s tailgate striker <i>new</i>			80.00	+
29	2pcs	Rear n/s tail gate number plate lamp <i>new</i>			120.00	+
30	1 pc	Rear n/s windscreen sealant <i>new</i>		80.00	60	
31	1 pc	Rear n/s windscreen moulding <i>new</i>		150.00	✓	
32	1 pc	Rear lock assembly <i>new</i>			516.50	+

33	1 pc	Rear end panel <i>Rep</i>			384.80	
34	1 pc	Rear end panel iner trim <i>Crackd</i>			136.60	
35	1 pc	Rear tail gate '70KM' emblem <i>Yan</i>		15.00	✓	
36	1 pc	Rear tail gate '5' PAX emblem		15.00	✓	
37	1 pc	Rear Nissan emblem <i>ru</i>			88.20	
38	1 pc	Rear reverse sensor <i>Dented</i>		280.00	<i>200(SN)</i>	
39	1 pc	Front bumper <i>Dented</i>			750.40	<i>54</i>
40	12 pc	Front bumper clips <i>ru</i>		60.00	<i>30</i>	
41	1 pc	Front bumper sponge <i>Crackd</i>			110.20	
42	1 pc	Front enforement <i>Dented</i>			245.40	
43	2pcs	Front o/s & n/s bumper top garnish <i>Dented</i>			441.60	
44	2pcs	Front bumper o/s & n/s retainer <i>ru</i>			126.70	
45	2pcs	Front o/s & n/s head lamp <i>Crackd</i>			1,296.80	
46	1 pc	Front grill <i>Crackd</i>			520.50	
47	1 pc	Front grill emblem <i>ru</i>			82.20	
48	1 pc	Front bonnet <i>Dented</i>			1,144.80	<i>86x</i>
49	1 pc	Front number plate <i>Best</i>		45.00	<i>30</i>	
50	1 pc	Front number plate bracket <i>Dented</i>		29.00	✓	
		<i>8217.60</i>	Sub Total:	0.00	1066.00	12,123.50
		<i>7355.84</i>		30%	0%	10%
		<i>S.N. 789</i>	After Less %:	0.00	1066.00	10,911.15
		Labour				
1		To dismantle damaged parts, straighten & welding.		1,600.00	<i>1200</i>	
2		To spray painting.		1,400.00	<i>1000</i>	
3		To remove & replace/refit rear o/s & n/s tail gate door. <i>fitty</i>		140.00	<i>120</i>	
4		To remove & refit rear tail gate o/s windscreen. <i>3</i>		130.00	<i>60</i>	
5		To remove & refit rear tail gate n/s windscreen. <i>3</i>		130.00	<i>60</i>	
6		To remove and replace rear reverse sensor		50.00	✓	
7		To check wiring.		80.00	<i>60</i>	
8		To re seal anti rust.		150.00	<i>60</i>	
		<i>2610</i>	Sub Total:		3,680.00	
			Total:		15,657.15	
			After less 20%		12,525.72	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call

Mobil 1



- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: