

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5127A*Not Authorized
Phongy B4pam***AAD2111-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

TOTAL PARTS SHC5127A

JTDKB3FUX03093087

TOYOTA

PRIUS GEN 4

05/11/2021

China

30/11/2020

08 NOV 2021

PART		LIST	
1	COVER, FRONT BUMPER	\$ CM 521.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ SVR 110.50	7X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ B 716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$ B 246.10	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$ CM 132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$ CM 80.20	✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$ SVR 80.10	7X
1	EXTENSION, FRONT BUMPER, RH	\$ SVR 120.10	7X
1	COVER, FRONT BUMPER HOLE, RH	\$ M 30.20	✓
1	MOULDING, FRONT BUMPER SIDE, RH	\$ M 95.60	✓
1	GRILLE SUB-ASSY, RADIATOR	\$ M 422.50	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$ CM 178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$ M 105.80	✓
1	JAR ASSY, WINDSHIELD WASHER	\$ SVR 219.10	7X
1	UNIT ASSY, HEADLAMP, RH	\$ M 2,637.60	✓
1	LAMP ASSY, FOG, RH	\$ SVR 237.10	7X
1	LINER, FRONT FENDER, RH	\$ S 202.50	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ S 241.90	X

TOTAL \$ 6,378.20**25% \$ 1,594.55****\$ 4,783.65****Special Nett**

1SET BUMPER CLIP FRT	\$ M 95.00	50%
1SET FRNT BUMPER RETAINER CLIP	\$ M 85.00	X
1 FR FLOOR UNDERCOVER CLIP	\$ M 65.00	X
1 FENDER LINER CLIP	\$ M 70.00	X
TOTAL \$	245.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5127A

AAD2111-

TOTAL PARTS \$ 5,028.65**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *600*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *4* 480.00 *X*

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *4* 480.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *4* 380.00 *X*

To check steering geometry and computer wheel alignment

\$ *4* 220.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *4* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *660*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5127A**AAD2111-**

To transfer of tire, rim and on wheel balancing.

\$ *na* 220.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *4* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *4* 380.00 X**TOTAL** \$ **8,670.00****Over All Total** \$ **13,698.65****(PART-BY-PART) Repair Days***25 DAYS**3 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: