

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5127A***Not Authorized  
Phongy B4pam***AAD2111-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**TOTAL PARTS SHC5127A 2,018.65**

JTDKB3FUX03093087

TOYOTA

PRIUS GEN 4

05/11/2021

China

30/11/2020

**08 NOV 2021**

	<b>PART</b>		<b>LIST</b>	
1	COVER, FRONT BUMPER	\$	CPM 521.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	110.50	?
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	B <sub>1</sub> 716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	B <sub>1</sub> 246.10	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM 132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	CM 80.20	✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	80.10	?
1	EXTENSION, FRONT BUMPER, RH	\$	120.10	?
1	COVER, FRONT BUMPER HOLE, RH	\$	mi 30.20	✓
1	MOULDING, FRONT BUMPER SIDE, RH	\$	mi 95.60	✓
1	GRILLE SUB-ASSY, RADIATOR	\$	mi 422.50	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM 178.60	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	mi 105.80	✓
1	JAR ASSY, WINDSHIELD WASHER	\$	219.10	?
1	UNIT ASSY, HEADLAMP, RH	\$	mi/CM 2,637.60	✓
1	LAMP ASSY, FOG, RH	\$	237.10	?
1	LINER, FRONT FENDER, RH	\$	sm 202.50	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	sm 241.90	X

**TOTAL \$ 6,378.20****25% \$ 1,594.55****\$ 4,783.65****Special Nett**

1SET BUMPER CLIP FRT	\$	mi 95.00	same
1SET FRNT BUMPER RETAINER CLIP	\$	mi 85.00	X
1 FR FLOOR UNDERCOVER CLIP	\$	mi 65.00	X
1 FENDER LINER CLIP	\$	mi 70.00	X
<b>TOTAL</b>	<b>\$</b>	<b>245.00</b>	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5127A

AAD2111-

**TOTAL PARTS \$ 5,028.65****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *600*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *4* 480.00 *X*

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *4* 480.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *4* 380.00 *X*

To check steering geometry and computer wheel alignment

\$ *4* 220.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *4* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *660*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

**Trans-cab Auto Services Pte Ltd****AAD2111-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5127A**

To transfer of tire, rim and on wheel balancing. \$ *na* 220.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair. \$ *4* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. \$ *4* 380.00 X

**TOTAL** \$ **8,670.00**

**Over All Total** \$ **13,698.65**

**(PART-BY-PART) Repair Days** *25 DAYS*

*3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: