

Not Authorized
Phony B4 paint

Trans-cab Auto Services Pte Ltd

AAD2111-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9910Z

Vehicle No.:

SHD9910Z

Chassis No.:

JTDKB3FU903093274

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS GEN 4

Date of Accident :

30/10/2021

Third Party Insurer :

ATG.

Date of Registration:

30/12/2020

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	REFLECTOR ASSY, REFLEX, RH
1	LAMP ASSY, REAR, RH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
1	PANEL SUB-ASSY, BODY LOWER BACK

	LIST	
\$	485.60	✓
\$	332.70	X
\$	374.50	✓
\$	118.30	X
\$	132.60	✓
\$	39.00	X
\$	293.60	X
\$	339.60	X
\$	261.00	✓
\$	651.00	X
TOTAL \$	3,027.90	
25% \$	756.98	
\$	2,270.93	

Special Nett

- 1 REAR BUMPER SIDE CLIP
- 1 TAIL LAMP CLIP
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER RETAINER CLIP

\$	60.00	50sm
\$	70.00	X
\$	700.00	X
\$	85.00	X
\$	75.00	X
TOTAL \$	990.00	

TOTAL PARTS \$ 3,260.93

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2111-005

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9910Z

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	Nn	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601	
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	4001	
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	Nn	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	4401	
To reinstall rear bumper parking sensor.	\$	170.00	501	
To transfer of tire, rim and on wheel balancing.	\$	170.00	Nn	X
To Check Electrical Lighting Concerned.	\$	170.00	201	
To check steering geometry and computer wheel alignment	\$	220.00	Nn	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	170.00	Nn	X
TOTAL	\$	5,500.00		
Over All Total	\$	8,760.93		

(PART-BY-PART) Repair Days

20 Days

3day1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: