

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100%

⏴

⏵

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA21011466/Euf3 Date: 10/11/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 5506P	Veh. Inspected	SHC 7291U
Policy No.	BVFCSB0007172114	Coverage (\$)	0.00
Claim No.	NSV2100149/HLF	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	10/11/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/11/2021	Inspection Date	10/11/2021
Survey held at	31 Corporation Rd, Singapore 649806		
Repairer	DING AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			