


Section A - Accident Details

Registration Number	SHB1208G
Case Reference Number	TAX/10/21/2067
Registration Date	23/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	LOW KIN FAI
Type of Accident	Head to Rear
Accident Date and Time	30/10/2021 11:13 AM
Accident Reported Date and Time	1/11/2021 9:51 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112895
Special Instruction to ARC, if any	TP/ DROVE IN M/ REAR PORTION/ NTUC - LKK
Prepared Date and Time	2/11/2021 2:56 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,200.00	\$250.00
Total Spray Cost	\$1,578.00	\$220.00
Total Spare Part Cost	\$5,132.13	\$1,032.46
Total Other Cost	\$1,530.00	\$230.00
TOTAL COST	\$12,440.13	\$1,732.46 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/11/2021 4:03 PM	03/11/2021 3:28 PM
Signature		
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2112-0176	Invoice Number	
Quotation Date	10.12.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$4,200.00	\$250.00
Total Labour	\$4,200.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY BUMPER BEAM	\$230.00	\$0.00
TO RESPRAY REAR PANEL	\$230.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$230.00	\$0.00
TO RESPRAY REAR MEMBER,RH	\$230.00	\$0.00
TO RESPRAY REAR MEMBER,LH	\$230.00	\$0.00
Total Spray Painting & Panel Beating	\$1,578.00	\$220.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,530.00	\$230.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10369261-SPRP	FASCIA-RR BPR	1.00	\$568.86	10.00	\$511.97	Replace	Replace
		10751490	FASCIA-RR BPR LWR	1.00	\$173.01	10.00	\$155.71	Replace	Replace
		10359003	FINISHER-RR BPR - RH	0.00	\$35.56	0.00	\$0.00	Replace	Not Given
		10359002	FINISHER-RR BPR - LH	0.00	\$35.56	0.00	\$0.00	Replace	Not Given
		10465727	BRACKET ASM-RR BPR FASCIA SI - RH	0.00	\$22.38	0.00	\$0.00	Replace	Not Given
		10465723	BRACKET ASM-RR BPR FASCIA SI - LH	0.00	\$22.38	0.00	\$0.00	Replace	Not Given
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$34.56	0.00	\$0.00	Replace	Not Given
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$34.56	0.00	\$0.00	Replace	Not Given
		10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.90	0.00	\$0.00	Replace	Not Given

✓
✓
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/12/2021

User ID : PohSuan

		10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.67	0.00	\$0.00	Replace	Not Given	X
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.67	0.00	\$0.00	Replace	Not Given	X
		10449056	BRACKET-RR BPR FASCIA LWR MTG - RH	0.00	\$9.60	0.00	\$0.00	Replace	Not Given	X
		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$9.60	0.00	\$0.00	Replace	Not Given	X
		90003417	SCRIVET-RR BPR FASCIA	10.00	\$0.63	10.00	\$5.67	Replace	Replace	√
		90003410	BOLT/SCREW-RR BPR FASCIA BRKT	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		50012569	NUT-RR BPR FASCIA BRKT	0.00	\$0.70	0.00	\$0.00	Replace	Not Given	X
		90003410	BOLT/SCREW-RR BPR FASCIA	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		90003375	NUT-RR BPR FASCIA	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		90004065	CLIP-RR BPR FASCIA	4.00	\$0.93	10.00	\$3.35	Replace	Replace	√
		10327894	BAR ASM-RR BPR IMP	1.00	\$253.48	10.00	\$228.13	Replace	Replace	√
		10450132	COVER-RR TOW HOOK OPG	0.00	\$5.07	0.00	\$0.00	Replace	Not Given	X
		10726677	LAMP ASM-RR FOG - RH	1.00	\$141.81	10.00	\$127.63	Replace	Replace	√
		10726676	LAMP ASM-RR FOG - LH	0.00	\$27.22	0.00	\$0.00	Replace	Not Given	X
		10376550	SENSOR-RR PARK DIST WSD	0.00	\$48.75	0.00	\$0.00	Replace	Not Given	X
		10395721	PANEL ASM-RR END SEPP	0.00	\$531.49	0.00	\$0.00	Replace	Not Given	X
		11031505	PANEL ASM-R/FLR R/SEAT SEPP	0.00	\$2,110.50	0.00	\$0.00	Replace	Not Given	X
		10799009	RAIL SUB ASM-R/CMPT SI - LH	0.00	\$722.74	0.00	\$0.00	Replace	Not Given	X
		10799055	RAIL SUB ASM-R/CMPT SI - RH	0.00	\$724.15	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total					\$5,580.95		\$1,032.46			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,032.46
 + 250.00
 + 450.00

 1,732.46