

(08/11/13) wef

ASS. REC. BY: *[Signature]*

REF:

NS/INC21011470/R1uc

367k

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SHB 5261A*at Workshop m/s *SMRT*of *60, Mercedes (and PK etc)*Insured: *NTUC* YN 7202T

Policy No.

Claims No. MT/1151064-002


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No:

*SHB 5261A*Yr Regn: *2017 / OCT*Type: M.Car / M.Cycle / Bus / Van / Lorry / *Taxi* / Prime Mover /

Truck / Trailer or

Make:

*TOYOTA PRINS HYBRID 1.8 CVT* c.c *1798*

Colour

*MAFON*

A/C: Insured / Std / NI / NA

Sp. Reading

*415214*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*STD KB 3FU 80 35 726 7.3*Gen. Cond: Good / *Fair* / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: Nil / *S/Rim* / STD A/Rim or

Tyre Size:

F:

R:

*195/65R15*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

*SAILUN*

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

*02/11/21*

D.O.I.

*03/11/21*

Survey held at

*SMRT*Des. of Damages *FR* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Confirmed L/S \$3950, 4 repair days.

(RED \$12477.41; 76%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 26/11 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \_S + RS\_ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : TP

Lump Sum / ~~TP~~ (\$ 3950

TOTAL

## Case Details

Case Reference Number :

TAX/11/21/2003

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5261A

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-16566-ID

Assigned By : Taxi Claims Manager  
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 02/11/2021 07:28 AM

Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	der
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	Xan
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	nn /
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Check	X nn
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	0	0	Not Give	Xm
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	Xan
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xan

Total Spare Part Cost 12,919.27

Surveyor Total 3,429.36

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,335.42

Final Sur Total 2,743.49

SMRT Recommendation											Surveyor Approval			
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	X nn
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	Xan
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Give	Xan
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Not Give	Xan
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Not Give	Xan
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	Xan
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Not Give	Xan
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	Xan
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	Xan
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace	bt
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	0	0	Not Give	Xan

Total Spare Part Cost 12,919.27

Surveyor Total 3,429.36

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,335.42

Final Sur Total 2,743.49



SMRT Recommendation											Surveyor Approval			
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	Xan
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Not Give	Xan
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	1	0	Repair	Xan
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Give	Xan
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	on
One Time Key In	Main			COMPUTER SUBASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	Xan
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	Xan

Total Spare Part Cost 12,919.27

Surveyor Total 3,429.36

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 10,335.42

Final Sur Total 2,743.49

SMRT Recommendation										Surveyor Approval				Remarks
DOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Not Give	yan
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	R
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	fan
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Not Give	fan
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	nu /
Total Spare Part Cost									12,919.27	Surveyor Total				3,429.36
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				20
Final Spare Part Cost									10,335.42	Final Sur Total				2,743.49

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,014.00	400	
Total:			1,014.00	400.00	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	80	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
Total:			1,314.00	680.00	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44	
Total:			928.44	178.44	

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>XAN</i>	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0 <i>XAN</i>	
5	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0 <i>XAN</i>	
6	Main	TO TOP UP A/C GAS	120.00	0 <i>XAN</i>	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>XAN</i>	
8	Main	TO WASH AND VACUUM	60.00	0 <i>XAN</i>	
Total:			928.44	178.44	

**LKK Auto Consultants** hence notify  
the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	10,335.42	2,743.49
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,314.00	680.00
Other	928.44	178.44
Overall Total	13,591.86	4,001.93
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	13,600.00	4,000.00
Surveyor Approved Amount		4,000.00
No of Repair Days*	7	4
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO.
Surveyor Name		Rasul
Signature		

Survey Date

03/11/2021

Save

Clear





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/11/2021 13:25 (SGT)
Date of Accident	02/11/2021 15:28 (SGT)
Exact Location of Accident	178 Bukit Panjang Rd, Singapore
Additional Location Information	DRIVE WAY OF BLK 178 BUKIT PANJANG ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5261A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	D-21097466MFSH
Cover Note Number	-

### DRIVER

Name of Driver	NG EE TEEN
NRIC No	SXXXX172H



Date Of Birth	24/12/1962
Occupation	Outdoor
Date Of Driving Pass	25/07/1983
Driving experience	38 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

MY TAXI WAS STATIONARY ALONG THE DRIVEWAY OF BLK 178 BUKIT PANJANG ROAD AS I WAS ALIGHTING MY PASSENGERS (FEMALE CHINESE) WHILST ONE PASSENGER ALIGHTED, ANOTHER WAS SEATED INSIDE COLLECTING CHANGE. SUDDENLY A LORRY YN7202T WHICH WAS PARKED IN FRONT OF MY TAXI, REVERSED AND HIT ONTO THE FRONT PORTION OF MY TAXI. AFTER WHICH THIRD PARTY CONTINUED TO DRIVE AWAY. I WENT AFTER THIRD PARTY AND MANAGED TO STOP HIM A DISTANCE AWAY.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7202T
Vehicle Manufacturer	-



2166

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	CHNG QWEE CHING
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

BLK 178 Bukit Panjang Road Drive way



A - SHB 5261A

B - YN7202T

**Describe Circumstances of the Accident**

Lined area for describing the circumstances of the accident.

**Declaration**

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

*[Signature]* 2/11/21

Driver's Signature (If driver is not the policyholder) / Date & Time

*[Signature]* 2/11/2021

Witness to the Reporting Centre  
Personal



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5261A
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS096813
Chassis No.:	JTDKKB3FU803572673
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Oct 2017
First Registration Date:	10 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	09 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$16,694.00
Total Rebate Amount:	\$20,444.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Nov 2021

OK