

Section A - Accident Details

Registration Number	SHB5261A
Case Reference Number	TAX/11/21/2003
Registration Date	10/10/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG EE TEEN
Type of Accident	Side Swipe
Accident Date and Time	2/11/2021 3:28 PM
Accident Reported Date and Time	2/11/2021 4:20 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112912
Special Instruction to ARC,if any	TP / FRONT PORTION / NTUC - LKK
Prepared Date and Time	3/11/2021 1:54 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,314.00	\$680.00
Total Spare Part Cost	\$13,170.97	\$3,681.07
Total Other Cost	\$928.44	(\$811.07)
TOTAL COST	\$16,427.41	\$3,950.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	10/11/2021 9:10 AM	09/11/2021 5:13 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	LUMP SUM REPAIR / AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2111-0206	Invoice Number	
Quotation Date	22.11.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,014.00	\$400.00
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$80.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,314.00	\$680.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$989.51)
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$928.44	(\$811.07)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		7531047060	EMBLEM ASSY FRONT	0.00	\$87.10	0.00	\$0.00	Replace	Not Given	X
		5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X
		5211447190	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Not Given	X
			NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X
			NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X
		5339547040	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given	X
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given	X
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given	X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/11/2021

User ID : PohSuan

		5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given	X
		5213247010	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Not Given	X
		5210347010	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	X
		5210247020	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given	X
		8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X
		8121047020	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X
		5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
		5330147110	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	√
		5334147040	INSULATOR, HOOD	0.00	\$393.90	0.00	\$0.00	Replace	Not Given	X
		5342047130	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
		5341047130	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
		5351047140	LOCK ASSY, HOOD	0.00	\$131.10	0.00	\$0.00	Replace	Not Given	X
		5328947072	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Not Given	X
		5320547900	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Not Given	X
		5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Not Given	X
		5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X
		5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X
		5321747030	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Not Given	X
		5321447050	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	X
		5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	100.00	\$0.00	Replace	Repair	R
		8118547691	UNIT, HEADLAMP, LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given	X
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	√
		5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Check	X
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	√
		5212747907	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X
		5212847906	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given	X
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	√
		8105647690	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given	X
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given	X
		1775337010	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Not Given	X
		5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	R
		5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X
		5387647110	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given	X
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	√
Total					\$15,610.00		\$3,429.37			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5310147080	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace
Total					335.60		251.70		

	3,681.07	
+	400.00	
+	858.44	L/S \$3,950/-
	4,939.51	
	-20%	
	3,951.61	