

REF: AG2/ 21011473/KV

ASSIGNMENT

10

Aspire 3

Page 1 / 2



FALCON-AIR

AARDWOLF PESTKARE (S) PTE LTD
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ATTN: YAN - 82688081

Attention: Motor Claim Department
Contact: 62681771

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg No.: 1995011400
GST Reg No.: 1995011400

Not Notified
11 Sep & 27 Oct
Resurvey After Pain
4 days

Estimate: ES012285

Date: 10/11/2021
Vehicle Num.: GBH 8059M
Make/Model: TOYOTA HIACE-2018
Chassis/Eng#: JTFHT02P700245289
Accident Date: 09/11/2021
Claim No.: C10012408
Reference: TP - NTUC AGT BUDGET DIRECT
Policy No.: 5123173745

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS: 1855
- 1 PC TAILGATE
 - 1 PC TAILGATE LOGO
 - 1 PC REAR BUMPER
 - 1 PC RH REAR BUMPER SIDE RETAINER
 - 1 PC RH TAILLAMP LOWER GARNISH

List Total S\$:
25.00% Discount S\$:

1,969.50 ✓
75.00 ✓
455.00 ✓
52.97 ✓
146.50 ✓
2,698.97
674.74
2,024.23

- SPECIAL NETT ITEMS:
- 1 PC 70 km/h STICKER
 - 10 PCS REAR BUMPER CLIP
 - 1 SET REVERSE SENSOR
 - 1 PC TAILGATE STICKER (COMPANY STICKER)

Special Nett Total S\$:

LABOUR:
TO REMOVE/REFIX TAILGATE GLASS
TO REMOVE/REFIX TAILGATE MECHANISM

121m 25.00 ✓
4.00 40.00 ✓
200.00 X
200.00 X
100
465.00
120.00 ✓
100.00 601

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk X) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co Reg No: 1995011400
GST Reg No: 1995011400

AARDWOLF PESTKARE (S) PTE LTD
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ATTN: YAN - 82688081

Attention: Motor Claim Department

Contact: 62681771

Estimate: ES012285

Date: 10/11/2021

Vehicle Num: GBH 8059M

Make/Model: TOYOTA HIACE-2018

Chassis/Eng#: JTFHT02P700245289

Accident Date: 09/11/2021

Claim No.: C10012408

Reference: TP - NTUC AGT BUDGET DIRECT

Policy No.: 5123173745

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO FIT REVERSE SENSOR INTO NEW BUMPER AND CHECK WIRING	50.00	201
		TO STRAIGHTEN REAR END PANEL INCLUDING REPLACEMENT OF PARTS	700.00	4001
		TO SPRAY PAINT ON TAILGATE, REAR END PANEL, REAR BUMPER RH TAILLAMP LOWER PANEL	900.00	7001
		Labour Total S\$:	1,870.00	

E. & O.E.

Total S\$: 4,359.23

=====

FALCON AIR AUTO SERVICES PTE LTD

quotation was prepared from visual inspection. Further materials and labour charges may be required when repair
manences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD

(A subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
ches: Tampines St 93 Blk 9006 #01-200 S(526840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg