

TPEQ
Veron

JSX-5338 2018 August.

Yamaha Y15ZR 150cc

PMYU60510J0166593

Front Fender Repair 95 X.

Front Wheel Rim. wt 280(SN) ✓

Front Fork Assy. Best 480 ✓

Front Fork Underbracket. ^{Dmgd} 125 ✓

Front. Fork oil New 30(SN) ✓

Steering Core and Bearing. ^{New} 75 ✓

Front Wing Mirror x 02 ^{RH} wt 48x2 = ~~96~~ 48.

Front Cowling. wt 125 ✓

Headlamp x 02 ^{new} 195 X

Headlamp Cowling x 02 ^{new} 75 X.

Front Side Fairing x 02 ^{could} 110 x 2 = 220 ✓

Yamaha Logo x 2 ^{new} 20 x 2 = 40 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JSX 5338

Front Signal Lamp x 02 ^{wt} 80 x L = 160. ✓

Brake Lever RH. ^{wt} 35. ✓

Foot Brake Pedal. ^{wt} 50 ✓

Front RH Footrest. ^{wt} 30. ✓

Exhaust Pipe Protector ^{wt} 85 ✓

Rear Box ^{wt} 250 (SN) ✓

Rear Box Bracket ^{MT} ^{MM} 200 (SN) +

1473 S.N.: 560.
132570

Panel Beating. ~~400~~ 200

Spray Painting. ~~300~~ 200

Wiring. ~~50~~ 30 470

Towing Fees. 40. ✓
1600

3436

Total: 235570

M/S: 18K.

04 Days