

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21011475/RTF3E2

Date: 02/03/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-423321-CA
Claimant Vehicle No :	SMS593B	Insured Vehicle No :	FBJ3297P
Date of Loss:	03/11/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS593B	Engine No:	L15B31021111
Make & Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Chassis No:	JHMGK5850GX202755
Reg. Date:	11/07/2016 (Man. Year: 2016)	Odometer:	61823 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,577.28	320.00	1,257.28	79.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	400.00	1,400.00	77.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,377.28	720.00	2,657.28	78.68
+ GST 7.00/7.00% (S\$)	236.41	50.40	186.01	78.68
Nett Amount (S\$)	3,613.69	770.40	2,843.29	78.68

INSPECTION

Date of Assignment:	10/11/2021		
Date Inspected:	12/11/2021	Inspected At:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$476.96 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMS593B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	329.40 FL	*329.40 FL
2	1		*REAR BUMPER GARNISH LH	Cracked	45.60 FL	*45.60 FL
3	1		*REAR BUMPER SIDE RETAINER LH	* Check	55.70 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	55.70 FL	*- FL
5	1		*REAR END PANEL	Not Necessary	540.50 FL	*- FL
6	1		*REAR TAILLAMP LH	* Check	540.50 FL	*- FL
7	1		*REAR TAILLAMP LOWER PANEL LH	Not Necessary	129.20 FL	*- FL
8	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
9	1		*REAR BUMPER SENSOR	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,916.60	395.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					339.32	75.00
Total Parts (\$\$)					1,577.28	320.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	200.00
2	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE	New	800.00	200.00
Gross Labour Cost (\$\$)			1,800.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >