



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
KARKAUNSL LEASINGS PTE LTD 1 SOON LEE ST PIONEER CENTRE #02-48SINGAPORE 627605		Ref: CS/TP21011476/Kqce2 Date: 16/12/2021 Code: TP540	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	WBSJF02080BW65306
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/11/2021
2. Vehicle Particulars & Condition			
Make & Model	BMW M5 (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBSJF02080BW65306	Colour	M. P. SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/35ZR20	MICHELIN	8 mm
L/H Front Tyre	275/35ZR20	MICHELIN	8 mm
R/H Rear Tyre	285/35ZR20	MICHELIN	8 mm
L/H Rear Tyre	285/35ZR20	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date		Inspection Date	09/11/2021
Survey held at	KARKAUNSL LEASINGS PTE LTD 1 SOON LEE STREET, #02-47, PIONEER CENTRE, SINGAPORE 627605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	