



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE #04-05 SIN MING AUTOCARE SINGAPORE 575721			Ref: CS/TP21011476/Kqce2 Date: 16/12/2021 Code: TP535	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	WBSJF02080BW65306	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	09/11/2021	
2. Vehicle Particulars & Condition				
	Make & Model	BMW M5 (A)	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WBSJF02080BW65306	Colour	M. P. SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/35ZR20	MICHELIN	8 mm
	L/H Front Tyre	275/35ZR20	MICHELIN	8 mm
	R/H Rear Tyre	285/35ZR20	MICHELIN	8 mm
	L/H Rear Tyre	285/35ZR20	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	Inspection Date	09/11/2021	
	Survey held at	KARKAUNSL LEASINGS PTE LTD 1 SOON LEE STREET, #02-47, PIONEER CENTRE, SINGAPORE 627605		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	