

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY, SINGAPORE 508734

VEHICLE NO : GBE7405U
MAKE & MODEL : NISSAN NV200
CHASSIS NO : VSKYBAM20Z0122023

DATE:
CLAIM TYPE :
D.O.A:

9 Nov 2021
OD CLAIM
3 Nov 2021

TO : INDIA INTERNATIONAL INSURANCE

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	FRONT BUMPER / BR		\$ 280.00	\$ 280.00
2	2	FRONT BUMPER LH / RH / BR		\$ 150.00	\$ 300.00
3	1	FRONT BUMPER SPONGE / BR		\$ 135.00	\$ 135.00
4	1	FRONT REINFORCEMENT / BR		\$ 350.00	\$ 350.00
5	2	FRONT BUMPER SIDE RETAINER LH / RH / BR		\$ 20.00	\$ 40.00
6	1	FRONT TOW COVER / MISC		\$ 20.00	\$ 20.00
7	1	BONNET / DD		\$ 450.00	\$ 450.00
8	1	BONNET LOCK / BT		\$ 45.00	\$ 45.00
9	2	BONNET HINGES LH / RH / X DD		\$ 35.00	\$ 70.00
10	1	FRONT GRILLE / BR		\$ 210.00	\$ 210.00
11	1	FRONT GRILLE LOWER MOULDING / BR		\$ 100.00	\$ 100.00
12	2	HEADLAMP ASSY LH / RH / BR		\$ 230.00	\$ 460.00
13	1	FRONT SUPPORT PANEL UPPER / DD		\$ 400.00	\$ 400.00
14	2	FRONT SUPPORT PANEL UPPER LH / RH / DD		\$ 60.00	\$ 120.00
15	2	RADIATOR AIR GUIDE UPPER LH / RH / CRV		\$ 45.00	\$ 90.00
16	2	RADIATOR AIR GUIDE LOWER LH / RH / CRV		\$ 45.00	\$ 90.00
17	1	RADIATOR / BR		\$ 430.00	\$ 430.00
18	1	CONDENSER / DD		\$ 430.00	\$ 430.00
19	1	RADIATOR FAN ASSY / X DD		\$ 450.00	\$ 450.00
20	1	RADIATOR FAN COWLING / BR		\$ 130.00	\$ 130.00
21	1	RADIATOR SPARE TANK / CRV		\$ 85.00	\$ 85.00
22	1	INTERCOOLER / BR		\$ 1,100.00	\$ 1,100.00
23	1	AIR CON LIQUID PIPE / BT		\$ 250.00	\$ 250.00
24	1	AIR CON DISCHARGE PIPE / BT		\$ 350.00	\$ 350.00
25	1	AIR CON SUCTION PIPE / X DD		\$ 200.00	\$ 200.00
26	1	AIR INTAKE AIR DUCT / BR		\$ 115.00	\$ 115.00
27	1	AIR DUCT / X DD		\$ 75.00	\$ 75.00
28	1	INTERCOOLER AIR INLET HOSE LH / CRV		\$ 140.00	\$ 140.00
29	1	INTERCOOLER AIR INLET HOSE RH / CRV		\$ 140.00	\$ 140.00
				\$ 6,470.00	\$ 7,055.00

TOTAL PRICE	\$ 7,055.00
COST PLUS 10%	\$ 705.50
SUB TOTAL PRICE	\$ 7,760.50

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS	✓ MK	\$ 50.00	\$ 50.00
2	1	FRONT GRILLE CLIPS	✓ MK	\$ 50.00	\$ 50.00
3	1	FRONT NUMBER PLATE	✓ MK	\$ 45.00	\$ 45.00
4	1	COOLANT	✓ MK	\$ 50.00	\$ 50.00
5	1	TOWING FEE	✓ MK	\$ 70.00	\$ 70.00

TOTAL S/NETT \$ **265.00** \$ **265.00**

Labour Charges

1	To cut & weld on support panel. To panel beat and straighten damaged panels	\$ 1,500.00	900
2	To putty and spray paint front damaged parts	\$ 1,000.00	30 600
3	To check and rectify wiring	\$ 50.00	50
4	To remove and replace radiator, condenser and to vacuum and top up air con gas	\$ 150.00	50

TOTAL LABOUR \$ **2,700.00**

Total Cost of Repairs \$ **10,725.50**

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK)
9/11/21, 11.00am

00-1111L
Excess - ?

PIP
by BL by
5 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: