

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 11 Nov 2021

**Preliminary Advice**

Vehicle No	: GBE7405U	Accident Date	: 03/11/2021
Make	: NISSAN NV200	Policy No.	: D19MFL0005549_02
Assignment Date	: 10/11/2021	Excess	: S\$0.00
Date of Inspection	: 09/11/2021	Est. Duration of Repair	: 5
Inspection At	: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ) 56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,725.50
Revised Amount	:S\$	8,626.00
Check Items (Estimated)	:S\$	405.00
Total	:S\$	9,031.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	16,446.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,554.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.