

ASS. REC. BY:

REF:

C12/210714911Ky

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SJY 5325E

at Workshop m/s Turn 150

of _____

Insured: GBL 1104R

Policy No. DMCVSNW00100032100

Claims No. SNM21D206340/C02


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6-7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 08/25

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJY 5325E Yr Regn: 09, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598Colour: n. Black A/C: Insured / Std / NI / NASp. Reading: 129101 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053888106175688Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 3/11/21 D.O.I. 11/11/2021

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ Car BLConfirmed L/S \$5300, 6 repair days
(RED \$5672.47; 52%)

Date/Time, File Pass to?

17/11 TYPIST

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum H.B. (\$) 5300

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Chong Tat Sen
958 Dunearn Road
#02-23
Singapore 589485

Vehicle No : SJY 5325 E
Make : Toyota Altis
Year : 2009

Not Authorized
1/1 Day &
Recovery After Paint
6-7 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s fender		<i>R</i> \$1,015.70 <i>X</i>
2 pcs	Rear n/s fender air vent	\$155.20	\$310.40 <i>?</i>
1 pc	Rear windscreen moulding		<i>na</i> \$110.10 <i>X</i>
2 pcs	Rear fender inner trim board	<i>Reborn / cmr</i> \$457.10	\$914.20 <i>✓</i>
2 pcs	Rear fender innershield	\$75.30	<i>sm</i> \$150.60 <i>X</i>
1 pc	Rear boot lid		<i>R</i> \$753.10 <i>✓</i>
2 pcs	Rear boot lid hinges	\$65.80	<i>R</i> \$131.60 <i>X</i>
1 pc	Rear boot lid inner lock		<i>na</i> \$157.20 <i>✓</i>
1 pc	Rear boot lid emblem " Logo "		<i>na</i> \$45.90 <i>✓</i>
1 pc	Rear boot lid emblem " Corolla "		<i>na</i> \$54.10 <i>✓</i>
1 pc	Rear boot lid emblem " Altis "		<i>na</i> \$45.20 <i>✓</i>
1 pc	Rear boot lid emblem " 1.6 E "		<i>na</i> \$36.30 <i>✓</i>
1 pc	Rear boot lid outer chrome handle		<i>way</i> \$255.10 <i>✓</i>
2 pcs	Rear no plate lamp	\$69.50	<i>sm</i> \$139.00 <i>X</i>
1 pc	Rear boot rubber		<i>ditto</i> \$181.70 <i>50cm</i>
2 pcs	Rear boot lid reflector	<i>ols ? n/s cda</i> \$115.20	<i>R</i> \$230.40 <i>✓</i>
1 pc	Rear end panel		<i>dit</i> \$605.70 <i>✓</i>
1 pc	Rear end panel inner garnish		<i>dit</i> \$197.50 <i>✓</i>
2 pcs	Rear tail-lamp assy	\$550.20	\$1,100.40 <i>?</i>
2 pcs	Rear tail-lamp panel	\$124.30	\$248.60 <i>?</i>
1 pc	Rear spare tyre panel		<i>R</i> \$755.90 <i>X</i>
1 pc	Rear spare tyre cover board		<i>way/dit</i> \$387.50 <i>✓</i>
1 pc	Rear bumper		<i>R</i> \$556.70 <i>✓</i>
2 pcs	Rear bumper bracket	\$156.30	\$312.60 <i>?</i>
1 pc	Rear bumper sponge		<i>cm</i> \$165.30 <i>✓</i>
4 pcs	Rear bumper side retainer	<i>dit</i> \$55.10	<i>ser</i> \$220.40 <i>X</i>
2 pcs	Rear bumper reflector	\$85.10	<i>pu</i> \$170.20 <i>X</i>
1 pc	Rear exhaust silencer		\$971.90 <i>?</i>

Less 25 %
balance c/f

\$10,223.30
\$2,555.83
\$7,667.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Y 5325 E

balance b/f \$7,667.47

S Nett

1 pc Rear no plate
1 set Rear reverse sensor
20 pcs Bumper clip

Rear camera

845d. ?

Labour Charges

Remove/renew the above parts including knocking, welding & cutting etc.

To putty & spray paint on rear accident affected portion.

Check/reconnect wiring.

To spray anti rust on accident affected portion.

Remove/renew rear exhaust silencer

Remove/refit rear windscreen to facilitate repair.

Ad \$45.00 ✓
Shan \$200.00 ✓
nu \$40.00 ✓
\$285.00

\$1,400.00 *8001*

\$1,200.00 *9001*

\$30.00 *201*

\$120.00 *601*

\$150.00 ?

nu \$120.00 X

Total \$10,972.47

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/11/2021 12:51 (SGT)
Date of Accident	03/11/2021 08:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE (TUAS) AT UPPER JURONG ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY5325E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHONG TAT SEN
NRIC No	S7375097J
Email Address	TATSEN@GMAIL.COM
Mobile Phone No	(Phone) +65-96222919
Alternative Phone No	+65-96222919

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119187026-01
Cover Note Number	-

DRIVER

Name of Driver	CHONG TAT SEN
NRIC No	S7375097J


 Accident report SN0721B30009

SKETCH PLAN

A-33753256

S-GBL104R

UPPER JUNG ROAD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to gear report

DECLARATION

We declare that reporting particulars are true in every respect.

Driver's Signature
Date & Time
03/11/24
D30821

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: SHAN
NRIC/IN No: 9990349