

Trust Autoworks

Mailing address Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Chong Tat Sen
958 Dunearn Road
#02-23
Singapore 589485

Vehicle No : SJY 5325 E
Make : Toyota Altis
Year : 2009

Not Authorised
61 Lp @ 5300hp
Penny After Paint
6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s fender		
2 pcs	Rear n/s fender air vent		
1 pc	Rear windscreen moulding	\$155.20	\$1,015.70 X
2 pcs	Rear fender inner trim board		\$310.40 X
2 pcs	Rear fender innershield		\$110.10 X
1 pc	Rear boot lid	\$457.10	\$914.20
2 pcs	Rear boot lid hinges	\$75.30	\$150.60
1 pc	Rear boot lid inner lock		\$753.10
1 pc	Rear boot lid emblem " Logo "	\$65.80	\$131.60 X
1 pc	Rear boot lid emblem " Corolla "		\$157.20
1 pc	Rear boot lid emblem " Altis "		\$45.90
1 pc	Rear boot lid emblem " 1.6 E "		\$54.10
1 pc	Rear boot lid outer chrome handle		\$45.20
2 pcs	Rear no plate lamp		\$36.30
1 pc	Rear boot rubber		\$255.10
2 pcs	Rear boot lid reflector	\$69.50	\$139.00 X
1 pc	Rear end panel	\$115.20	\$181.70
1 pc	Rear end panel inner garnish		\$230.40
2 pcs	Rear tail-lamp assy		\$605.70
2 pcs	Rear tail-lamp panel		\$197.50
1 pc	Rear spare tyre panel	\$550.20	\$1,100.40
1 pc	Rear spare tyre cover board	\$124.30	\$248.60
1 pc	Rear bumper		\$755.90 X
2 pcs	Rear bumper bracket		\$387.50
1 pc	Rear bumper sponge		\$556.70
4 pcs	Rear bumper side retainer	\$156.30	\$312.60
2 pcs	Rear bumper reflector		\$165.30
pc	Rear exhaust silencer	\$55.10	\$220.40
		\$85.10	\$170.20 X
			\$971.90 X
			\$10,223.30
			Less 25 %
			\$2,555.83
			balance c/f
			\$7,667.47

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Y 5325 E

S Nett

balance b/f \$7,667.47

1 pc Rear no plate
1 set Rear reverse sensor
20 pcs Bumper clip

	<i>Ad</i>	\$45.00	✓
	<i>Shor</i>	\$200.00	✓
\$2.00	<i>Re</i>	\$40.00	✓
		<u>\$285.00</u>	

Labour Charges

Rear corner

845d. ? 2803n short

Remove/renew the above parts including knocking, welding & cutting etc.

\$1,400.00 *800l*

To putty & spray paint on rear accident affected portion.

\$1,200.00 *900l*

Check/reconnect wiring.

\$30.00 *20l*

To spray anti rust on accident affected portion.

\$120.00 *60l*

Remove/renew rear exhaust silencer

nn \$150.00 *X*

Remove/refit rear windscreen to facilitate repair.

nn \$120.00 *X*

Total \$10,972.47