

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

10/11/2021 16:59

JOB-NO: 50113753

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0107R

TRANS: AUTO

CHASSIS: JTDKB3FU703079986

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR2C08843

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	1,400.00	0.00	1,400.00	800	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	1.00	350.00	0.00	350.00	50	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	280.00	0.00	280.00	30	Y	_____
5 TO REFIT REAR REVERSE SENSOR	1.00	160.00	0.00	160.00	30	Y	_____
6 TO REAPPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	200.00	0.00	200.00	X	Y	_____
7 TO TRANSFER REAR BOOT MECHANISM TO NEW BOOT AND PERFORM WATER SEEPAGE TEST	1.00	180.00	0.00	180.00	50	Y	_____
8 TO REMOVE AND REFIT REAR UPPER AND LOWER WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	1.00	260.00	0.00	260.00	200	Y	_____
9 TO REMOVE AND REFIT REAR EXHAUST TO ENABLE BODYWORK REPAIR	1.00	220.00	0.00	220.00	X	Y	_____
10 TO CHECK AND REPAIR WIRE HARNESS	1.00	220.00	0.00	220.00	X	Y	_____
11 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	50	Y	_____
13 TO RESPRAY REAR BUMPER EXTENSION FILLER	1.00	250.00	0.00	250.00	X	Y	_____
14 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	200	Y	_____
15 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	200	Y	_____
16 TO RESPRAY REAR TAILGATE OUTER GARNISH	1.00	250.00	0.00	250.00	150	Y	_____
17 TO RESPRAY REAR FLOOR PAN	1.00	250.00	0.00	250.00	?	Y	_____
TOTAL:		5,200.00	0.00	5,200.00			_____

MATERIALS

1 REAR BUMPER COVER / DD	1.00	442.60	110.65	331.95	L	Y	_____
2 REAR BUMPER CENTER GUARD / CR4	1.00	576.30	144.08	432.22	L	Y	_____
3 REAR LH BUMPER EXTENSION FILLER X	1.00	123.70	30.93	92.77	L	Y	_____
4 REAR RH BUMPER EXTENSION FILLER X	1.00	123.70	30.93	92.77	L	Y	_____
5 REAR BUMPER TOWING COVER / CR4	1.00	15.40	3.85	11.55	L	Y	_____
6 REAR RH BUMPER SIDE SEAL X	1.00	88.50	22.13	66.37	L	Y	_____
7 REAR BUMPER REINFORCEMENT / DD	1.00	332.70	83.18	249.52	L	Y	_____

(photo)

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
8 REAR LH BUMPER RETAINER	1.00	116.50	29.13	87.37	L	Y	
9 REAR TAILGATE PANEL ASSY	1.00	1,147.80	286.95	860.85	L	Y	
10 REAR TAILGATE OUTER GARNISH	1.00	925.60	231.40	694.20	L	Y	
11 REAR TAILGATE TOYOTA EMBLEM	1.00	47.90	11.98	35.92	L	Y	
12 REAR TAILGATE PRIUS EMBLEM	1.00	54.60	13.65	40.95	L	Y	
13 REAR TAILGATE HYBRID EMBLEM	1.00	54.60	13.65	40.95	L	Y	
14 REAR BOOT LOCK	1.00	467.00	116.75	350.25	L	Y	
15 REAR BOOT WEATHERSTRIP	1.00	372.30	93.08	279.22	L	Y	
16 REAR END PANEL	1.00	650.30	162.58	487.72	L	Y	
17 REAR END PANEL TRIM BOARD	1.00	126.70	31.68	95.02	L	Y	
18 REAR BUMPER CENTER UNDER COVER	1.00	229.90	57.48	172.42	L	Y	
19 REAR LH BUMPER UNDER COVER	1.00	241.90	60.48	181.42	L	Y	
20 REAR RH BUMPER UNDER COVER	1.00	175.10	43.78	131.32	L	Y	
21 REAR EXHAUST TAIL PIPE	1.00	1,649.00	412.25	1,236.75	L	Y	
22 REAR EXHAUST PIPE GASKET	1.00	53.50	13.38	40.12	L	Y	
23 REAR TAILGATE UPPER WINDSCREEN MOULDING	1.00	35.50	8.88	26.62	L	Y	
24 REAR TAILGATE UPPER WINDSCREEN ADHESIVE DAM	1.00	28.90	7.23	21.67	L	Y	
25 REAR TAILGATE LOWER WINDSCREEN MOULDING	1.00	23.60	5.90	17.70	L	Y	
26 REAR TAILGATE LOWER WINDSCREEN ADHESIVE DAM	1.00	28.90	7.23	21.67	L	Y	
27 REAR LH TAILGATE LOWER WINDSCREEN OUTER MOULDING NO.2	1.00	30.90	7.73	23.17	L	Y	
28 REAR RH TAILGATE LOWER WINDSCREEN OUTER MOULDING NO.2	1.00	30.90	7.73	23.17	L	Y	
29 TAILLAMP LOWER LH	1.00	502.00	125.50	376.50	L	Y	
30 TAILLAMP LOWER RH	1.00	502.00	125.50	376.50	L	Y	
31 REAR LH DECK FLOOR BOX	1.00	313.00	78.25	234.75	L	Y	
32 REAR RH DECK FLOOR BOX	1.00	313.60	78.40	235.20	L	Y	
33 REAR BUMPER CLIP SET	1.00	80.00	0.00	80.00	S	Y	
34 REAR BUMPER UNDER COVER CLIP SET	1.00	65.00	0.00	65.00	S	Y	
35 REAR REVERSE SENSOR SET	2.00	400.00	0.00	400.00	S	Y	
36 REAR BUMPER PROTECTOR	1.00	160.00	0.00	160.00	S	Y	
37 REAR BUMPER EXTENSION FILLER CLIP	1.00	55.00	0.00	55.00	S	Y	
38 REAR END PANEL SEALANT	2.00	160.00	0.00	160.00	S	Y	
39 REAR TAILGATE "6552-1111" STICKER	1.00	140.00	0.00	140.00	S	Y	
40 REAR TAILGATE "COMFORT DELGRO" STICKER	1.00	140.00	0.00	140.00	S	Y	
41 REAR TAILGATE "BOOK NOW" STICKER	1.00	140.00	0.00	140.00	S	Y	
42 REAR WINDSCREEN PRIMER	2.00	150.00	0.00	150.00	S	Y	
43 REAR WINDSCREEN GLASS PAD SET	1.00	55.00	0.00	55.00	S	Y	
44 REAR WINDSCREEN SEALANT	3.00	180.00	0.00	180.00	S	Y	
45 REAR TAILGATE OUTER GARNISH CLIP	1.00	65.00	0.00	65.00	S	Y	
46 REAR SPOILER CLIP AND PAD SET	1.00	55.00	0.00	55.00	S	Y	
47 REAR QUARTER PANEL ADVERTISEMENT STICKER	1.00	250.00	0.00	250.00	S	Y	
48 TAILLAMP GUIDE CLIP SET	1.00	55.00	0.00	55.00	S	Y	
49 REAR BUMPER RETAINER CLIP	1.00	55.00	0.00	55.00	S	Y	
TOTAL:		12,029.90	4,566.32	9,573.58			
TOTAL PARTS & LABOUR :		17,229.90	2,456.32	14,773.58			

EXCESS/LOADING:\$ \$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$ \$ _____

DATE OF SURVEY: ____ / ____ / ____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY:

Stere (LKK) 10/11/91, 5.09pm

WA AL

CONTACT NO:

FAX NO:

5 days

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

PIP

12, BL Sy

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Part by Part

Labour = \$	1990.00
S/N = \$	590.00
Parts = \$	3919.75
LtStP = \$	6499.75
Final Amt = \$	6499.75