



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

not Authorised

11 November 2021

REG NO.: SMQ 5629 K
MAKE/MODEL: HYUNDAI AVANTE

d/s \$4100
4 days *whisper after 4 days*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Rear boot lid <i>Bodily 20</i> <i>1782</i>	\$ 1,853.60 ✓
1	Rear boot inner trim <i>11</i>	\$ 235.60 X
2	Rear boot lamps <i>n/scre o/s n 294</i>	\$ 1,374.60 <i>1pc</i>
1	Rear boot lock <i>Y m 145</i>	\$ 234.00 ✓
1	Rear boot logo <i>ner 42</i>	\$ 169.70 ✓
1	Rear boot rubber <i>11 48</i>	\$ 300.30 X
1	Rear boot "S" emblem <i>ner 35</i>	\$ 92.40 ✓
1	Rear boot "AVANTE" emblem <i>ner</i>	\$ 97.90 ✓
2	Rear taillamps <i>n/scre o/s n 362.50</i>	\$ 2,179.20 <i>1pc</i>
1	Rear end panel <i>2</i>	\$ 657.80 X
1	Rear end panel inner garnish <i>8m</i>	\$ 175.90 X
1	Rear bumper <i>20/20 m</i>	\$ 459.40 ✓
2	Rear bumper side brackets <i>11</i>	\$ 161.80 X
1	Rear bumper clip (1 set) <i>ner</i>	\$ 50.00 ✓
1	Rear bumper inner sponge <i>NF</i>	\$ 166.30 X
1	Rear bumper reflector <i>115 cre 202</i>	\$ 359.00 ✓
1	Rear bumper reinforcement <i>cre</i>	\$ 294.80 ✓
1	Rear bumper: <i>centre garnish Torn</i>	\$ 339.60 ✓
2	Rear number plate lamps <i>11</i>	\$ 112.60 X
1	Rear view camera <i>11</i>	\$ 582.60 X
1	Rear floor board <i>11</i>	\$ 397.80 X
1	Rear floor panel <i>11</i>	\$ 798.60 X
1	Rear exhaust silencer <i>11</i>	\$ 756.20 X
2	Rear exhaust mountings <i>11</i>	\$ 97.00 X
		\$ 11,946.70
Less 20%		\$ 2,389.34
		\$ 9,557.36

SPECIAL NETT ITEMS

1	Rear number plate with holder	\$	50.00	40
1	Rear reverse sensor (1 set)	\$	350.00	200
		\$	400.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
5	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	120
6	To apply undercoating.	\$	150.00	30
7	Panel beating.	\$	1,600.00	580
8	To re-spray painting on the affected areas.	\$	1,500.00	820
		\$	3,900.00	

GRAND TOTAL :

\$ 13,857.36

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4054-3
202
P-3243-44
S.N-240
L-1680
5133-44
202
4106