

AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MAO HWEE CHING

c/o 46 Lenton Plain
Singapore 786548

Not Authorized
1/10/2011
Recurring After Paint
12 days
1/10/2011 @ 17,500/- Max

Date: 11/Nov/21

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: MERCEDES BENZ A200 / SFY 300 G		
1 pc	rear boot lid <i>1750</i>	<i>Bz</i> 1,964.00 ✓
1 pc	rear boot lid inner trim	<i>Sn</i> 538.00 ✗
1 pc	rear boot emblem 'logo'	<i>Mc</i> 94.00 ✓
1 pc	rear end panel <i>1210.45</i>	<i>Bz</i> 1,745.00 ✗
1 pc	rear end panel garnish	<i>Sn</i> 547.00 ✗
1 pc	rear fender air drafter	<i>Ad</i> 145.00 ✗
1 pc	rear fender <i>1560-10</i>	<i>Bz</i> 1,750.00 ✗
1 pc	rear fender dust cover	<i>Sn</i> 432.00 ✗
1 pc	rear fender inner trim	<i>Sn</i> 578.00 ✗
1 pcs	rear bumper park sensor <i>@ 225.00</i>	<i>Shen</i> 1,188.00 ✓
1 pc	rear bumper tow cover	<i>mis</i> 68.00 ✓
1 pc	rear bumper reinforcement	<i>R</i> 684.00 ✗
1 pc	rear bumper centre retainer	<i>Sn</i> 296.00 ✗
1 set	rear park sensor wire harness assy	<i>tn</i> <i>Sn</i> 368.00 ✓
1 pc	rear exhaust silencer <i>1850</i>	<i>Bz</i> 1,946.00 ✓
1 pc	rear exhaust heat shield <i>268.35</i>	<i>Bz</i> 854.00 ✓
1 pc	rear tail lamp assy <i>625</i>	<i>Sn</i> 846.00 ✓
1 pc	rear lower arm <i>187.40</i>	<i>Bz</i> 845.00 ✓
1 pc	rear toe control arm	<i>mis</i> 241.00 ✓
1 pc	rear trailing control arm <i>268</i>	<i>mis</i> 469.00 ✓
1 pc	rear camber control arm	<i>Bz</i> 295.00 ✓
1 pc	rear knuckle arm <i>695</i>	<i>Bz</i> 765.00 ✓
1 pc	rear under sub frame cross member <i>1787.5</i>	<i>Bz</i> 2,410.00 ✓
1 pc	rear wheel bearing hub assy	<i>Mc</i> 360.00 ✓
1 pc	rear shock absorber <i>695</i>	<i>Bz</i> 740.00 ✓
1 pc	parking brake control unit	<i>Sn</i> 860.20 ✗
2 pcs	front bumper park sensor <i>@ 396.00</i>	<i>Sn</i> 792.00 ✗
1 pc	front bumper top inner pad	<i>Sn</i> 325.00 ✗
1 pc	front bumper reinforcement	<i>R</i> 587.00 ✗
1 pc	front bumper top emblem	<i>Mc</i> 86.00 ✓
1 pc	front top grille outer trim <i>460</i>	<i>Ad</i> 984.00 ✓
sub-total		23,802.20

	Balance carried forward.		23,802.20	
1 pc	front top grille emblem <i>132</i>		<i>short</i> <i>Red</i> 325.00	✓
1 pc	front top grille sensor <i>506</i>		<i>Red</i> 596.00	X ✓
1 pc	front top grille inner mash		<i>Red</i> 394.00	✓
1 pc	front head lamp <i>2150-30</i>		<i>mg/NT</i> 3,745.00	✓
1 pc	front head lamp washer nozzle cover		<i>Sn</i> 296.00	X
1 pc	front number plate support bracket		<i>n</i> 96.00	X
1 pc	radiator air guild deflector		<i>Sn</i> 98.00	X
		Sub-total	29,352.20	
		Less 5%	1,467.61	
		Sub-total	27,884.59	
1 pc	rear windscreen glass inner seal	s.nett	<i>Me</i> 78.00	<i>30sn</i>
1 set	rear exhaust tip pipe cutter <i>325</i>	s.nett	<i>Ry</i> 650.00	✓
1 pc	rear bumper <i>1650</i>	s.nett	<i>CM/Ry</i> 1,650.00	✓
1 pc	rear bumper lower pad	s.nett	<i>mis</i> 762.00	✓
1 pc	rear bumper side garnish	s.nett	<i>CM</i> 315.00	✓
1 pc	rear bumper side retainer	s.nett	<i>CM</i> 64.00	✓
1 pc	front bumper <i>1658</i>	s.nett	<i>Bu</i> 1,658.00	✓
1 pc	front bumper side grille	s.nett	<i>Sn</i> 196.00	X
1 pc	front bumper side grille inner pad	s.nett	<i>Sn</i> 186.00	X
1 pc	front bumper side grille trim	s.nett	<i>Sn</i> 365.00	X
1 pc	front bumper lower centre grille	s.nett	<i>Sn</i> 398.00	X
1 pc	front numper plate	s.nett	<i>Ry</i> 35.00	<i>345sn</i>
1 pc	front number plate casing	s.nett	35.00	
1 pc	alloy rim	s.nett	<i>Sn</i> 980.00	X
1 tube	windscreen glasss sealant	s.nett	<i>Me</i> 60.00	<i>40sn</i>
1 pc	tyre- 225/45R17 headking	s.nett <i>111.20sn</i>	<i>Pu</i> 278.00	<i>408sn</i>
		Sub-total	35,594.59	
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,600.00	<i>1000l</i>
	To check wiring system.		60.00	<i>40l</i>
	To apply rust proofing on affected areas.		150.00	<i>30l</i>
	To carry exhaust works.		150.00	<i>60l</i>
	To remove and replace rear undercarriage parts.		450.00	<i>240l</i>
	To spray painting on affected areas.		1,400.00	<i>1000d</i>
	To apply waterproof sealant on affected areas.		160.00	<i>20l</i>
		Sub-total	39,564.59	

Balance carried forward.	39,564.59	
To install reverse sensors.	80.00	500
To remove and refit rear windscreen glass.	140.00	1200
To remove carpet,trimming and seats to enable to repair.	100.00	800
TP replace alloy rim & perform wheel balancing.	40.00	200
To perform 4 wheels computerised alignment.	85.00	600
Towing.- 1 accident to ARC / 2. ARC to workshop. King dolly.	(B.11) 240.00	720
Total	40,249.59	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: