

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
8 Kaki Bukit Ave 4 #08-45/46
Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444

TO	: CHINA TAIPING (EZ31P)	DATE	: 12-Nov-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	: SXXXX701E	VEHICLE NO.	: SBQ4009L
Veron.		MODEL / MAKE	: LEXUS RX300
		CHASSIS NO.	: JTJZAMCA902082487
		ACCIDENT DETAIL	
		DATE	: 25-Oct-21
		TIME	: 18:20HRS

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>behind</i>	1	\$ 991.00	\$ 991.00
2	REAR BUMPER REFLECTOR RH <i>new</i>	1	\$ 49.00	\$ 49.00
3	REAR BUMPER REFLECTOR GARNISH RH <i>new</i>	1	\$ 181.00	\$ 181.00
4	REAR BUMPER LOWER DIFFUSER <i>tan new</i>	1	\$ 708.00	\$ 708.00
5	REAR BUMPER REVERSE SENSOR RH <i>new</i>	1	\$ 488.00	\$ 488.00
6	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	\$ 20.00	\$ 80.00
7	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET <i>new</i>	1	\$ 118.00	\$ 118.00
8	REAR BUMPER EXHAUST END CHROME PIPE RH <i>new</i>	1	\$ 269.00	\$ 269.00
9	REAR BUMPER SIDE RETAINER LH/RH <i>RH new</i>	2	\$ 151.00	\$ 302.00
10	REAR BUMPER LOWER SIDE BRACKET LH/RH <i>new</i>	2	\$ 202.00	\$ 404.00
11	REAR BUMPER INNER SPONGE <i>2</i>	1	\$ 128.00	\$ 128.00
12	REAR FENDER ARCH GARNISH LH/RH <i>2 new</i>	2	\$ 115.00	\$ 230.00
13	REAR FENDER INNER AIR VENT RH <i>1 new</i>	1	\$ 173.00	\$ 173.00
14	REAR FENDER INNER SHIELD RH	1	\$ 326.00	\$ 326.00
TOTAL PRICE				\$ 4,447.00
LESS -10%				\$ (444.70)
SUB TOTAL PRICE				\$ 4,002.30

1323
1190.70

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
3	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00
4	REAR FENDER ARCH GARNISH CLIPS SET LH/RH <i>2 new</i>	2	\$ 50.00	\$ 100.00
5	REAR FENDER INNER SHIELD CLIPS SET LH/RH <i>2 new</i>	2	\$ 60.00	\$ 120.00
TOTAL				\$ 300.00

30

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 750.00	250	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 750.00	250	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 150.00	50	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 380.00	X	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 280.00	X	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	X	

TOTAL \$ 2,790.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	4,302.30
TOTAL LABOUR COST	:	\$	2,790.00
TOTAL REPAIR COST	:	\$	7,092.30

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMP SUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	
CONTACT NUMBER	:	
EMAIL ADDRESS	:	
DATE / TIME OF RE-SURVEY	:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
4/5 12/11/21
02 Days

total: 180070

2/5: 1.41K ✓

Vehicle not repaired

580