



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLL3186Y

Lim Swee Hon Robin

Blk 70A Telok Belangah Heights
#18-509
Singapore 101070

Mobile: +6598321062

Vehicle & Document Information
WIP No 53301
Reg No/Reg Date SLL3186Y / 22/06/2016
Date In/Mileage
Chassis No WDD1173422N347209
Engine No 27091030926797
Make/Model MB/MB CLA 180 COUPE (C117) "URBAN"
Colour/Trim 027 761 Polar Silv/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	09/11/2021/ 18:35	YK	395 / Yik Chan Hoe
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : P10380262R01 // 08/11/2021				
DRIVE IN/EXCESS : 09/11/2021 // TP VEH NO SML7688M CHINA TAIPING				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
S BPNSUB				
TRANSFER TYRES OVER TO NEW RIMS X 2				120.00 ✓
A BPILAB				
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH				1970 2400.00
A BPIRES				
RESPRAY FRONT BUMPER AND LEFT FRONT FENDER				1200 1800.00 ✓
A BPILAB				
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT				0.10 380.00 ✓
A BPILAB				
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT				120.00 ✓
A BPILAB				
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT				540.00 ✓
M LEFT & RIGHT FRONT DISK WHEEL				
M LEFT HEADLAMP - CUT				2.00 ✓ 688.68 00.00 1377.36 ✓
M FRONT BUMPER - CUT				1.00 2632.90 00.00 2632.90 ✓
M FRONT BUMPER - BR				1.00 1421.95 00.00 1421.95 ✓
M FRONT BUMPER MB EMBLEM - nec				1.00 63.68 00.00 63.68 ✓
M LEFT FRONT DISTANCE SENSOR - nec				1.00 182.48 00.00 182.48 ✓
M PTS SPACER RING - nec				1.00 6.35 00.00 6.35 ✓
M LEFT FRONT FENDER - nec				1.00 683.73 00.00 683.73 ✓
M LEFT FRONT FENDER INTERMEDIATE LAYER - nec				1.00 17.94 00.00 17.94 ✓

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chenhoe.yik@cyclecarriage.com.sg

Nett 11,746.39
7% GST on 11746.39 822.25

Total Payable 12,568.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg