

ASS. REG. BY: Steve

CC4/LPC21011530/ra3

ASSIGNMENT

From: Dolo
 Estimated Cost: _____
 To Inspect Vehicle No: _____
 at Workshop no: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____
 (Client's Record)
 Make of Vehicle: _____

(Policy Condition)
 Remarks: The vehicle has commenced its repair at the time of inspection.

Det. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 SIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Vol.: Yes or No
 QA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time: _____ Action / Instruction

MR-540K

Time/Date, File, Remarks: ☐ Prelim. Report
☐ Final Report

Time/Date, File, Remarks:

Remarks: _____
 any other remarks: _____

Vehicle: SDR 1988 G Year: 13/4/21
 Type: M. Cycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or _____
 Make: Porsche Taycan
 Color: Grey A/C: _____ Insured / Stolen / N
 Sp. Reading: 9709 Tyres: Insured / Stolen / N
 Eng. No: _____
 Chassis: WPOZZLY1ZM SA00-778
 Gen. Cond: Good / Fair / Poor / Bught
 Steering: Free / Jammed / Locked / Burnt or
 Brakes: Free / Jammed / Locked / Burnt or
 Mod: M / S / B / L / G / O / A / R / M /
 Tyre Size: P1 285/40 R20
 RI: 11
 BU / DUH / EX / NOVA / GY / FS / LIZA / MIC / OHTSV / PIR / SUM /
 TOYO / YOKO or Pirelli
 Front: _____ Rear: _____
 R/Wal: 5 mm R/Wal: 5 mm
 L/Wal: 5 mm L/Wal: 5 mm
 D.O.A.: 27/10/21 Trans Eurekaars
 Survey held at: _____
 Des. of Damages: FR / Rear / C/S / H/S / VIC / Roof / or
Rear RH
 The V/O / CHASSIS frame / Body Structure affected due to collision

Days of Repair: _____

Resurvey No. or Trips: _____

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ VV/eval (\$)

Survey Fee:
 Transportation

Survey Fee:

Survey Fee:

Survey Fee:

Survey Fee:

Survey Fee:



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042 EUROKARS GROUP
ESTIMATE COST OF REPAIRS

LONPAC INSURANCE BHD 300 Beach Road, #17-04/07 The Concourse Singapore 199555 ATTN.: MOTOR CLAIMS FAX:		NAME: ADDRESS: TEL:		WIP: 23568 EXCESS: DATE: 10-Nov-21	
VEH NO:	SDQ1988G	DATE IN:		CONTACT PERSON:	JOB: 63310682
CHASSIS NO:	WP0ZZZY1ZMSA00778	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY
MODEL:	Porsche Taycan	DATE REG.:	13-Apr-21	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description		QTY	1ST	SUPP	REVISED	PRICES
1	REAR BUMPER	CRU	1				\$ 1,940.60
2	REAR BUMPER LOWER TRIM	BR	1				\$ 898.20
3	SENSOR BRACKET LH	MC	1				\$ 50.30
4	SENSOR BRACKET RH	MC	1				\$ 50.30
5	SENSOR GASKET	MC	4				\$ 12.40
6	SENSOR		4				\$ 1,016.00
7	REAR BUMPER CLIPS	MC	4				\$ 8.80
8	BRACKET FOR SENSOR	MC	1				\$ 52.10
9	REAR BUMPER CENTER BRACKET		1				\$ 161.70
10	HEADLIGHT BRACKET RH		1				\$ 98.80
11	REAR BUMPER GUIDE RH		1				\$ 79.70
12	REAR BUMPER BRACKET FOR DIFFUSER		1				\$ 34.60
13	BRACKET FOR LOWER TRIM		1				\$ 42.80
14	REAR BUMPER REINFORCEMENT		1				\$ 1,497.00
15	REAR BUMPER SPONGE		1				\$ 137.70
16	REAR BOOTLID	X R	1				\$ 3,687.30
17	BLIND RIVET NUT	MC	6				\$ 33.00
18	TYCAN LOGO	MC	1				\$ 269.50
19	REAR LIGHT REFLECTOR RH	BR	1				\$ 133.50
20			0				\$ -
TOTAL PARTS							\$ 10,204.30
TOTAL PARTS COST							\$ 10,204.30

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
Labour Description							
1	TO REMOVE /REPLACE REAR BUMPER, REINFORCEMENT, BOOTLID & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.						\$ 3,900.00

1560

	O RESPRAY REAR BUMPER, REAR BOOT. 1300 + 1120			\$	2,600.00	7400
	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$	250.00	150
4	TO TRANSFER THE REVERSE SENSORS.			\$	300.00	150
5	TO TRANSFER THE REVERSE CAMERA.		NETT	\$	200.00	100
6	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)		NETT			
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$	250.00	150
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$	600.00	✓
9	TO SUPPLY AND INSTALL BODY WRAP STICKER (PRICE TO BE ADVISE)		NETT			
10	SUNDRIES.		NETT	\$	50.00	70
		TOTAL LABOUR		\$	-	\$ 8,150.00
		TOTAL PARTS		\$	-	\$ 10,204.30
		TOTAL		\$	-	\$ 18,354.30
		LESS EXCESS		\$	-	\$ -
		TOTAL AFTER EXCESS		\$	-	\$ 18,354.30
		GST 7%		\$	-	\$ 1,284.80
		GRAND TOTAL		\$	-	\$ 19,639.10

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Steve (LKK)
15/11/21, 12:30pm

WML
4 dys
P/P
My BL sy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: