

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 09 Dec 2021

Preliminary Advice

Insured : GBJ8674B
Vehicle No
TP Vehicle : GBD3616J Accident Date : 05/11/2021
No
Make : HYUNDAI H-1 STAREX Assignment Date : 11/11/2021
Date of : 08/12/2021 Est. Duration of : 3
Inspection Repair
Inspection At : SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
(PIONEER)
BLK 3 PIONEER ROAD NORTH, #01-18
SINGAPORE 628457

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,201.20
Revised Amount	:S\$	2,330.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,330.64

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.