

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chee So Chow

Date: 12 Nov 2021

Preliminary Advice

Vehicle No	: GBL5822A	Accident Date	: 09/11/2021
Make	: NISSAN NV350	Policy No.	: DMCVSNW00136472100
Assignment Date	: 11/11/2021	Excess	: S\$350.00
Date of Inspection	: 12/11/2021	Est. Duration of Repair	: 5
Inspection At	: Z-ONE AUTOMOTIVE PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6, BLK D #01-87, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,227.80
Revised Amount	:S\$	3,887.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,887.54
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	31,681.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,319.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.