



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21011539/Evy3 Date: 11/11/2021 Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PC 4310Z	Veh. Inspected	FBJ 8578X	
Policy No.	DMB1SNW00011792100	Coverage (\$)	0.00	
Claim No.	SNM21D206268/C02/LEEPG	Excess (\$)	0.00	
Assign From	CECILIA LEE PENG GEOK	Assign Date	11/11/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/10/2021	Inspection Date	12/11/2021	
Survey held at	BLK 1008 BUKIT MERAH LANE 3, #01-14			
Repairer	SPEEDWAY MOTOR PL			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				