



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2106513

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 17/09/2021  
Reference CS3/GRB21009571/R1tf3e2  
Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. FBK 3092H Bill cancel refer to new invoice No. AC2108832 23/12/2021 \$261.00  
Insured Veh. SMA 6632C  
Claim No. MFL2021D0003864  
Policy No. D21MFL0000447  
Accident Date 05/09/2021  
Inspection Date 14/09/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 14.09.2021 04.10pm	
Merimen Fee	11.00
<b>Subtotal</b>	<b>131.00</b>
<b>GST (7%)</b>	<b>9.17</b>
<b>Grand Total</b>	<b>140.17</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2108832

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 23/12/2021  
Reference CS3/GRB21009571/R1tf3e2-  
'  
Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. FBK 3092H  
Insured Veh. SMA 6632C  
Claim No. MFL2021D0003864  
Policy No. D21MFL0000447  
Accident Date 05/09/2021  
Inspection Date 14/09/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
**Note: Pls discard Inv.AC2106513 dated 17/09/2021 \$140.17**	
<b>Subtotal</b>	<b>261.00</b>
<b>GST (7%)</b>	<b>18.27</b>
<b>Grand Total</b>	<b>279.27</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**