

Vinon Law

M78-116110

MCS AUTO

1100 Serangoon Road Singapore 328195

Company Registration No. 53126812L

Email : mcs.auto@yahoo.com.sg

Date: 27 Oct 2021

Mohamed Hameem Mohamed Kassim

C/O MCS AUTO

1100 Serangoon Road Singapore 328195

FINAL REPAIR COSTS

VEHICLE NO: FBK3092H (BAJAJ PULSAR 200 NS FI)

Repair costs of vehicle no. FBK3092H as per the surveyor's
report KTO AUTOMOBILE ASSESSORS (attached herewith)

dated 18 Oct 2021

\$3,700.00

LUMP SUM

SINGAPORE DOLLARS : THREE THOUSAND SEVEN HUNDRED ONLY

