

VEHICLE NO : FBK 3092 H
MAKE/MODEL: BAJAJ PULSAR 200 NS FI

Our Ref : TP/MCS/FBK3092H/8580

C)	<u>LABOUR CHARGES</u>			
39	Towing service charge. (2 Trips)	\$	80.00	\$ 80.00 40
40	To conduct front body frame alignment.	\$	280.00	\$ 180.00 80
41	Replace, realign & adjust above damaged parts. Check wiring & lighting system.	\$	450.00	\$ 350.00 300
	Labour Total :	\$	810.00	\$ 610.00 420
	Total Parts and Labour	\$	4,968.50	\$ 4,680.00

FINAL LUMP SUM ADJUSTMENT \$ 3,700.00

REMARKS
The repairer has agreed to undertake repair the vehicle at a lump sum basis of **\$3,700.00 nett** corresponding to replacement of parts and labour charges. We now revert for your decision on the above claim.

1562.40
450.00
420.00

2432.40
20%
1945.92
L/S-\$1,950/4DAYS

Yours faithfully
KTO Automobile Assessors


Ong Ah Keng (CAE, AMIMI, MSAAA)
Automotive Appraiser