

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0914/2021/JT
DATE : 9-Nov-21
WIP : 52295

Veron.
\$6139.76.
04 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NG KOK WAH
ADDRESS : 9 TAMPINES STREET 86
#12-27 QBAY RESIDENCES
SINGAPORE 528587
TELEPHONE : HP +65 96190345
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800061529-02
VEHICLE NO : SFV 2818 H
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 2/6/2018
ENGINE NO : CVK 060539
CHASSIS NO : WAUZZZF40JA159718
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Nov-21
PLACE OF ACCIDENT : ALONG JALAN EUNOS TOWARDS
EUNOS LINK TURNING TO PIE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 2818 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$	480.00	X. ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X.
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	2,100.00 1000	✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00 1100	✓
5	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00 280	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$	<u>5,642.00</u>

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 2818 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 1,787.00	✓ 1429.60
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	TBC	X
3	FRONT BUMPER SECURING STRIPS <i>Not Nec</i>	2	\$ 71.00	? X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Not Nec</i>	1	\$ 210.00	+
5	FRONT AIR GUIDE - LH <i>Neu</i>	1	\$ 63.00	X
6	FRONT AIR GUIDE GRILLE - LH	1	\$ 135.00	+
7	FRONT BUMPER GUIDE SECTION - LH <i>Not Nec</i>	1	\$ 36.00	? X
8	FRONT FENDER - LH <i>Denier</i>	1	\$ 767.00	✓ 613.20
9	FRONT FENDER ATTACHEMENT PARTS <i>Neu</i>	1	\$ 202.00	X
10	FRONT FENDER CLOSING ELEMENT - LH <i>Not Nec</i>	1	\$ 72.00	? X
11	FRONT FENDER BRACKET - LH <i>Not Nec</i>	1	\$ 35.00	? X
12	FRONT FENDER BRACKET SUPPORT - LH <i>Not Nec</i>	1	\$ 118.00	? X
13	FRONT FENDER BRACKET DEFORMATION ELEMNT - LH <i>Not Nec</i>	1	\$ 49.00	? X
14	FRONT FENDER REAR BRACKET - LH <i>Not Nec</i>	1	\$ 32.00	? X
15	FRONT FENDER WHEEL HOUSING - LH <i>Neu</i>	1	\$ 240.00	+
16	FRONT FENDER WHEEL HOUSING ATTACHEMENT PART	1	TBC	
17	FRONT WHEEL SPOILER <i>Neu</i>	1	\$ 73.00	+
18	FRONT SPOILER - LH <i>Neu</i>	1	\$ 35.00	X
19	FRONT FENDER TRIM PROTECTION - LH <i>Neu</i>	1	\$ 31.00	? 24.64
20	FRONT FENDER UPPER TRIM PROTECTION - LH <i>Neu</i>	1	\$ 23.00	? 17.92
SUB TOTAL SPARE PARTS		:	\$ 3,979.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 2818 H

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT LED HEADLIGHT - LH <i>new</i>	1	\$ 7,693.00	+
22	FRONT HEADLIGHT WASHER - LH	1	\$ 210.00	+
23	FRONT TYRE <i>new</i>		TBC	+
24	FRONT TYRE RIM <i>lt</i>		TBC	✓ 980
25	SUNDRIES <i>Neu</i>	1	\$ 250.00	? 22.40
TOTAL SPARE PARTS		:	\$ 12,132.00	
TOTAL LABOUR CHARGES		:	\$ 5,642.00	
GRAND TOTAL		:	\$ 17,774.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adnan King*
 SURVEYED DATE : *10/11/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT