

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0914/2021/JT
DATE : 09-Nov-21
WIP : 52295

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 29 Dec 21

OWNER'S NAME : MR NG KOK WAH
ADDRESS : 9 TAMPINES STREET 86
#12-27 QBAY RESIDENCES
SINGAPORE 528587
TELEPHONE : HP +65 96190345
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800061529-02
VEHICLE NO : **SFV 2818 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 02/06/2018
ENGINE NO : CVK 060539
CHASSIS NO : WAUZZZF40JA159718
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 05-Nov-21
PLACE OF ACCIDENT : ALONG JALAN EUNOS TOWARDS
EUNOS LINK TURNING TO PIE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFV 2818 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,642.00	\$	3,052.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 2818 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,787.00	\$ 1,429.60
2	FRONT BUMPER FIXING PARTS	1	TBC	
3	FRONT BUMPER SECURING STRIPS	2	\$ 71.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 210.00	
5	FRONT AIR GUIDE - LH	1	\$ 63.00	
6	FRONT AIR GUIDE GRILLE - LH	1	\$ 135.00	
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00	
8	FRONT FENDER - LH	1	\$ 767.00	\$ 613.20
9	FRONT FENDER ATTACHEMENT PARTS	1	\$ 202.00	
10	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 72.00	
11	FRONT FENDER BRACKET - LH	1	\$ 35.00	
12	FRONT FENDER BRACKET SUPPORT - LH	1	\$ 118.00	
13	FRONT FENDER BRACKET DEFORMATION ELEMENT - LH	1	\$ 49.00	
14	FRONT FENDER REAR BRACKET - LH	1	\$ 32.00	
15	FRONT FENDER WHEEL HOUSING - LH	1	\$ 240.00	
16	FRONT FENDER WHEEL HOUSING ATTACHEMENT PART	1	TBC	
17	FRONT WHEEL SPOILER	1	\$ 73.00	
18	FRONT SPOILER - LH	1	\$ 35.00	
19	FRONT FENDER TRIM PROTECTION - LH	1	\$ 31.00	\$ 24.64
20	FRONT FENDER UPPER TRIM PROTECTION - LH	1	\$ 23.00	\$ 17.92
SUB TOTAL SPARE PARTS		:	\$ 3,979.00	\$ 2,085.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFV 2818 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 2,085.36
21	FRONT LED HEADLIGHT - LH	1	\$ 7,693.00	
22	FRONT HEADLIGHT WASHER - LH	1	\$ 210.00	
23	FRONT TYRE		TBC	
24	FRONT TYRE RIM		TBC	\$ 980.00
25	SUNDRIES	1	\$ 250.00	\$ 22.40
TOTAL SPARE PARTS			: \$ 12,132.00	\$ 3,087.76
TOTAL LABOUR CHARGES			: \$ 5,642.00	\$ 3,052.00
GRAND TOTAL			: \$ 17,774.00	\$ 6,139.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.