

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0920/2021/JT
DATE : 10-Nov-21
WIP : 52708

\$23414.44

08 Days

Veron.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN QIU HAO, ASHLEY
ADDRESS : 7C BISHOPGATE
SINGAPORE 249975
TELEPHONE : HP +65 91875336
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210054279
VEHICLE NO : SDQ 3339 S
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 9/11/2021
ENGINE NO : CZD C37976
CHASSIS NO : WAUZZZF33M1105583
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Nov-21
PLACE OF ACCIDENT : JERVOIS ROAD BEFORE BISHOPGATE
(OUTSIDE CONDO DORMER PARK)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 3339 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 2,000.00	✓ ✓
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY BOTH FRONT DOOR.	S/N \$ 280.00	X.
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDERS AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2500 2250 Bumper 1 Bonnet 1 Lock Carrier 2.5 4.5
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 6,000.00	2875 ✓ 4.5 x 550 = 2475 Painted Arc 200 x 2 = 400 2875
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		\$ 15,144.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 636 - 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,335.00	✓ 1068
2	FRONT BUMPER CONNECTING PIECE <i>Not nec</i>	1	\$ 145.00	? X
3	FRONT BUMPER FIXING PARTS <i>Not nec</i>	1	\$ 414.00	X
4	FRONT BUMPER CLOSING ELEMENT - RH <i>Not nec</i>	1	\$ 59.00	? X
5	FRONT BUMPER TRIM - MANHATTAN GREY <i>ut</i>	1	\$ 356.00	✓ 284.40
6	FRONT BUMPER LOWER GRILLE - CENTER <i>lit</i>	1	\$ 217.00	✓ 173.20
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH INNER <i>Not nec</i>	2	\$ 50.00	X
8	FRONT BUMPER LOWER GRILLE CAP <i>Not nec</i>	1	\$ 51.00	? X
9	FRONT BUMPER CLOSING ELEMENT <i>Not nec</i>	1	\$ 190.00	? X
10	FRONT BUMPER LOWER SPOILER <i>cracked</i>	1	\$ 763.00	✓ 610
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not nec</i>	1	\$ 153.00	? X
12	FRONT BUMPER TRIM - RH MANHATTAN GREY <i>Not nec</i>	1	\$ 164.00	? X
13	FRONT PARKING AID SENSOR BRACKET - RH <i>Not nec</i>	1	\$ 25.00	? X
14	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,928.00	✓ 1542.40
15	RADIATOR STRIKER PLATE ? ✓ <i>Damaged</i>	1	\$ 244.00	? 194.80
16	FRONT "360" DEGREE CAMERA CAP <i>Not nec</i>	1	\$ 56.00	X
17	FRONT "360" DEGREE CAMERA BRACKET <i>Not nec</i>	1	\$ 41.00	X
18	RADIATOR TOP COVER ? <i>cracked</i>	1	\$ 244.00	? 194.80
19	FRONT "360" DEGREE CAMERA <i>new</i>	1	\$ 1,141.00	X
20	FRONT BUMPER FOAM FILLER PIECES <i>Not nec</i>	1	\$ 102.00	? X
SUB TOTAL SPARE PARTS		:	\$ 7,678.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER REINFORCEMENT BEAM <i>? dented</i>	1	\$ 916.00	<i>? 732.40</i>
22	FRONT BUMPER GUIDE SECTION - RH <i>Not nec</i>	1	\$ 39.00	<i>? X</i>
23	FRONT BUMPER TOP COVER <i>? cracked</i>	1	\$ 123.00	<i>? 98</i>
24	"CAUTION" STICKER <i>? nec</i>	2	\$ 28.00	<i>? 16.56</i>
25	AIR COND STICKER <i>? nec</i>	1	\$ 8.00	<i>? 5.68</i>
26	FRONT PARKING AID SENSOR <i>Not nec</i>	3	TBC	<i>X</i>
27	FRONT PARKING AID SENSOR SEAL RING <i>Not nec</i>	4	\$ 9.00	<i>X</i>
28	FRONT BUMPER WIRING SET <i>Not nec</i>	1	\$ 572.00	<i>X</i>
29	SIGNAL HORN LOW TONE - RH <i>Not nec</i>	1	\$ 130.00	<i>X</i>
30	SIGNAL HORN BRACKET - RH <i>Not Nec</i>	1	\$ 22.00	<i>? X</i>
31	FRONT FENDER - RH <i>Repair</i>	1	\$ 1,286.00	<i>X</i>
32	FRONT FENDER ATTACHEMENT PARTS <i>Not nec</i>	1	\$ 63.00	<i>X</i>
33	FRONT FENDER BRACE - RH <i>? Not nec</i>	1	\$ 88.00	<i>X</i>
34	FRONT FENDER BRACKET - RH <i>? Not nec</i>	1	\$ 32.00	<i>X</i>
35	FRONT FENDER CLOSING ELEMENT - RH <i>? Not nec</i>	1	\$ 33.00	<i>X</i>
36	FRONT WHEEL HOUSING LINER - RH <i>? Not nec</i>	1	TBC	<i>X</i>
37	FRONT WHEEL HOUSING ATTACHEMENT PARTS <i>? Not nec</i>	1	\$ 101.00	<i>X</i>
38	FRONT WHEEL HOUSING COVER - RH	1	\$ 16.00	<i>X</i>
39	BONNET <i>Dented</i>	1	\$ 3,508.00	<i>✓ 2806.40</i>
40	BONNET HINGES - LH / RH <i>Not Nec</i>	2	\$ 146.00	<i>? X</i>
SUB TOTAL SPARE PARTS		:	\$ 7,120.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (CK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NIRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET ATTACHEMENT PARTS	1	\$ 296.00	X
42	BONNET STRIKER - RH	1	\$ 110.00	X
43	BONNET SOUND ABSORBER	1	\$ 219.00	X
44	BONNET IMPACT PROTECTION - CENTER HEAVY cracked	1	\$ 28.00	✓ 21.84
45	FRONT FENDER TOP COVER - RH HEAVY	1	\$ 41.00	X
46	PLENUM CHAMBER COVER HEAVY	1	\$ 129.00	X
47	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
48	BONNET LID LOCK MICROSWITCH - RH	2	\$ 214.00	X
49	BONNET LATCH	1	\$ 58.00	X
50	BONNET RELEASE LEVER	1	\$ 14.00	X
51	BONNET BOWDEN CABLE CAP	1	\$ 10.00	X
52	HEADLIGHT MOUNTING - RH ? cracked	1	\$ 118.00	? 94.40
53	LED HEADLIGHT - RH cracked	1	\$ 5,589.00	✓ 4471.20
54	HEADLIGHT ELECTRONIC POWER MODULE - RH HEAVY	1	\$ 758.00	X
55	HEADLIGHT HEAT SINK - RH HEAVY	1	\$ 781.00	X
56	LIFT CYLINDER - RH HEAVY	1	\$ 210.00	X
57	LIFT CYLINDER HOSE - RH HEAVY ✓ <i>ht.</i>	1	\$ 80.00	X 63.44
58	LOCK CARRIER cracked	1	\$ 1,272.00	✓ 1017.60
59	RADIATOR COOLANT HEAVY	6	\$ 266.00	✓ 212.64
60	RADIATOR AIR GUIDE - RH ? deformed	1	\$ 38.00	? 29.76
SUB TOTAL SPARE PARTS		:	\$ 10,289.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - UPPER / LOWER [✓] ? torn	2	\$ 84.00	42.00 33.04
62	OUTSIDE TEMPERATURE SENSOR HOLDER <i>Not m</i>	1	\$ 7.00	*
63	FRONT WHEEL ARCH COVER - LH / RH <i>Nec</i>	2	\$ 1,072.00	✓ 857.60
64	FRONT WINDOW SLOT SEAL - RH <i>Not m</i>	1	\$ 224.00	+
65	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60.39
66	SUNDRIES <i>Nec.</i>	1	\$ 400.00	? 31.68
TOTAL SPARE PARTS		:	\$ 26,934.00	
TOTAL LABOUR CHARGES		:	\$ 15,144.00	
GRAND TOTAL		:	\$ 42,078.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408599

TEL : 6366 2323 FAX : 6641 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 10/11/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 08 Days.
S.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT