

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0920/2021/JT  
**DATE** : 10-Nov-21  
**WIP** : 52708

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR TAN QIU HAO, ASHLEY  
**ADDRESS** : 7C BISHOPGATE  
SINGAPORE 249975  
**TELEPHONE** : HP +65 91875336  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210054279  
**VEHICLE NO** : **SDQ 3339 S**  
**MODEL CODE** : AUDI Q3 SB 1.4 TFSI  
**MODEL YEAR** : 9/11/2021  
**ENGINE NO** : CZD C37976  
**CHASSIS NO** : WAUZZZF33M1105583  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 8-Nov-21  
**PLACE OF ACCIDENT** : JERVOIS ROAD BEFORE BISHOPGATE  
(OUTSIDE CONDO DORMER PARK)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 3339 S**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 2,000.00	✓
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY BOTH FRONT DOOR.	S/N \$ 280.00	X
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDERS AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2250 Bumper 1 Bonnet 1 Lock Carrier 2.5
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 6,000.00	2875 4.5 x 550 = 2475 Hatched Arc 200 x 2 = 400 4.5
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 15,144.00</b>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 636 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,335.00	✓
2	FRONT BUMPER CONNECTING PIECE ?	1	\$ 145.00	?
3	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 414.00	X
4	FRONT BUMPER CLOSING ELEMENT - RH ?	1	\$ 59.00	?
5	FRONT BUMPER TRIM - MANHATTAN GREY <i>ut</i>	1	\$ 356.00	✓
6	FRONT BUMPER LOWER GRILLE - CENTER <i>ut</i>	1	\$ 217.00	✓
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH INNER <i>new</i>	2	\$ 50.00	X
8	FRONT BUMPER LOWER GRILLE CAP ?	1	\$ 51.00	?
9	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 190.00	?
10	FRONT BUMPER LOWER SPOILER <i>cracked</i>	1	\$ 763.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - RH ?	1	\$ 153.00	?
12	FRONT BUMPER TRIM - RH MANHATTAN GREY ?	1	\$ 164.00	?
13	FRONT PARKING AID SENSOR BRACKET - RH ?	1	\$ 25.00	?
14	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,928.00	✓
15	RADIATOR STRIKER PLATE ?	1	\$ 244.00	?
16	FRONT "360" DEGREE CAMERA CAP <i>new</i>	1	\$ 56.00	X
17	FRONT "360" DEGREE CAMERA BRACKET <i>new</i>	1	\$ 41.00	X
18	RADIATOR TOP COVER ? <i>cracked</i>	1	\$ 244.00	?
19	FRONT "360" DEGREE CAMERA <i>new</i>	1	\$ 1,141.00	X
20	FRONT BUMPER FOAM FILLER PIECES ?	1	\$ 102.00	?
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 7,678.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER REINFORCEMENT BEAM ? dented	1	\$ 916.00	?
22	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 39.00	?
23	FRONT BUMPER TOP COVER ? cracked	1	\$ 123.00	?
24	" CAUTION " STICKER ? nec	2	\$ 28.00	?
25	AIR COND STICKER ? nec	1	\$ 8.00	?
26	FRONT PARKING AID SENSOR <i>not new</i>	3	TBC	x
27	FRONT PARKING AID SENSOR SEAL RING <i>not new</i>	4	\$ 9.00	x
28	FRONT BUMPER WIRING SET <i>not new</i>	1	\$ 572.00	x
29	SIGNAL HORN LOW TONE - RH <i>not new</i>	1	\$ 130.00	x
30	SIGNAL HORN BRACKET - RH ?	1	\$ 22.00	?
31	FRONT FENDER - RH <i>Repair</i>	1	\$ 1,286.00	x
32	FRONT FENDER ATTACHEMENT PARTS <i>not new</i>	1	\$ 63.00	x
33	FRONT FENDER BRACE - RH { <i>not new</i>	1	\$ 88.00	x
34	FRONT FENDER BRACKET - RH { <i>not new</i>	1	\$ 32.00	x
35	FRONT FENDER CLOSING ELEMENT - RH { <i>not new</i>	1	\$ 33.00	x
36	FRONT WHEEL HOUSING LINER - RH { <i>not new</i>	1	TBC	x
37	FRONT WHEEL HOUSING ATTACHEMENT PARTS { <i>not new</i>	1	\$ 101.00	x
38	FRONT WHEEL HOUSING COVER - RH	1	\$ 16.00	x
39	BONNET <i>Dented</i>	1	\$ 3,508.00	✓
40	BONNET HINGES - LH / RH ?	2	\$ 146.00	?
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 7,120.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: N@RA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET ATTACHEMENT PARTS	1	\$ 296.00	X
42	BONNET STRIKER - RH	1	\$ 110.00	X
43	BONNET SOUND ABSORBER	1	\$ 219.00	X
44	BONNET IMPACT PROTECTION - CENTER <del>HEAT</del> cracked	1	\$ 28.00	X
45	FRONT FENDER TOP COVER - RH	1	\$ 41.00	X
46	PLENUM CHAMBER COVER	1	\$ 129.00	X
47	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
48	BONNET LID LOCK MICROSWITCH - RH	2	\$ 214.00	X
49	BONNET LATCH	1	\$ 58.00	X
50	BONNET RELEASE LEVER	1	\$ 14.00	X
51	BONNET BOWDEN CABLE CAP	1	\$ 10.00	X
52	HEADLIGHT MOUNTING - RH ? cracked	1	\$ 118.00	?
53	LED HEADLIGHT - RH cracked	1	\$ 5,589.00	✓
54	HEADLIGHT ELECTRONIC POWER MODULE - RH	1	\$ 758.00	X
55	HEADLIGHT HEAT SINK - RH	1	\$ 781.00	X
56	LIFT CYLINDER - RH	1	\$ 210.00	X
57	LIFT CYLINDER HOSE - RH	1	\$ 80.00	X
58	LOCK CARRIER	1	\$ 1,272.00	✓
59	RADIATOR COOLANT	6	\$ 266.00	✓
60	RADIATOR AIR GUIDE - RH ? deformed	1	\$ 38.00	?
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 10,289.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - UPPER / LOWER <i>✓ 7 torn</i>	2	\$ 84.00	<i>7 42.00</i>
62	OUTSIDE TEMPERATURE SENSOR HOLDER <i>Not m</i>	1	\$ 7.00	<i>+</i>
63	FRONT WHEEL ARCH COVER - LH / RH <i>Nec</i>	2	\$ 1,072.00	<i>✓</i>
64	FRONT WINDOW SLOT SEAL - RH <i>Not m</i>	1	\$ 224.00	<i>+</i>
65	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>
66	SUNDRIES <i>?</i>	1	\$ 400.00	<i>?</i>
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 26,934.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 15,144.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 42,078.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King  
 SURVEYED DATE : 10/11/21  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS : Not Authorised, 08 Days.

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT