

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0920/2021/JT
DATE : 10-Nov-21
WIP : 52708

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

8 days - ok - Johnny Boo

15-Dec-21

OWNER'S NAME : MR TAN QIU HAO, ASHLEY
ADDRESS : 7C BISHOPGATE
SINGAPORE 249975
TELEPHONE : HP +65 91875336
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210054279
VEHICLE NO : **SDQ 3339 S**
MODEL CODE : AUDI Q3 SB 1.4 TFSI
MODEL YEAR : 9/11/2021
ENGINE NO : CZD C37976
CHASSIS NO : WAUZZZF33M1105583
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Nov-21
PLACE OF ACCIDENT : JERVOIS ROAD BEFORE BISHOPGATE
(OUTSIDE CONDO DORMER PARK)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 3339 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. TO RENEW ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	2,000.00	\$	2,000.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY BOTH FRONT DOOR.	S/N \$	280.00		
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDERS AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(Q3 L/Carrier x 3 days)</i>	\$	5,600.00	\$	2,500.00
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS.	\$	6,000.00	\$	2,875.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 15,144.00	\$	8,297.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,335.00	\$	1,068.00
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00		
3	FRONT BUMPER FIXING PARTS	1	\$ 414.00		
4	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 59.00		
5	FRONT BUMPER TRIM - MANHATTAN GREY	1	\$ 356.00	\$	284.40
6	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 217.00	\$	173.20
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH INNER	2	\$ 50.00		
8	FRONT BUMPER LOWER GRILLE CAP	1	\$ 51.00		
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00		
10	FRONT BUMPER LOWER SPOILER	1	\$ 763.00	\$	610.00
11	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 153.00		
12	FRONT BUMPER TRIM - RH MANHATTAN GREY	1	\$ 164.00		
13	FRONT PARKING AID SENSOR BRACKET - RH	1	\$ 25.00		
14	RADIATOR GRILLE	1	\$ 1,928.00	\$	1,542.40
15	RADIATOR STRIKER PLATE	1	\$ 244.00	\$	194.80
16	FRONT "360" DEGREE CAMERA CAP	1	\$ 56.00		
17	FRONT "360" DEGREE CAMERA BRACKET	1	\$ 41.00		
18	RADIATOR TOP COVER	1	\$ 244.00	\$	194.80
19	FRONT "360" DEGREE CAMERA	1	\$ 1,141.00		
20	FRONT BUMPER FOAM FILLER PIECES	1	\$ 102.00		
SUB TOTAL SPARE PARTS			\$ 7,678.00	\$	4,067.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 4,067.60</i>
21	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 916.00	<i>\$ 732.40</i>
22	FRONT BUMPER GUIDE SECTION - RH	1	\$ 39.00	
23	FRONT BUMPER TOP COVER	1	\$ 123.00	<i>\$ 98.00</i>
24	" CAUTION " STICKER	2	\$ 28.00	<i>\$ 16.56</i>
25	AIR COND STICKER	1	\$ 8.00	<i>\$ 5.68</i>
26	FRONT PARKING AID SENSOR	3	TBC	
27	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	
28	FRONT BUMPER WIRING SET	1	\$ 572.00	
29	SIGNAL HORN LOW TONE - RH	1	\$ 130.00	
30	SIGNAL HORN BRACKET - RH	1	\$ 22.00	
31	FRONT FENDER - RH	1	\$ 1,286.00	
32	FRONT FENDER ATTACHEMENT PARTS	1	\$ 63.00	
33	FRONT FENDER BRACE - RH	1	\$ 88.00	
34	FRONT FENDER BRACKET - RH	1	\$ 32.00	
35	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 33.00	
36	FRONT WHEEL HOUSING LINER - RH	1	TBC	
37	FRONT WHEEL HOUSING ATTACHEMENT PARTS	1	\$ 101.00	
38	FRONT WHEEL HOUSING COVER - RH	1	\$ 16.00	
39	BONNET	1	\$ 3,508.00	<i>\$ 2,806.40</i>
40	BONNET HINGES - LH / RH	2	\$ 146.00	
SUB TOTAL SPARE PARTS			\$ 7,120.00	\$ 7,726.64

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 7,726.64</i>
41	BONNET ATTACHEMENT PARTS	1	\$ 296.00	
42	BONNET STRIKER - RH	1	\$ 110.00	
43	BONNET SOUND ABSORBER	1	\$ 219.00	
44	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00	<i>\$ 21.84</i>
45	FRONT FENDER TOP COVER - RH	1	\$ 41.00	
46	PLENUM CHAMBER COVER	1	\$ 129.00	
47	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	
48	BONNET LID LOCK MICROSWITCH - RH	2	\$ 214.00	
49	BONNET LATCH	1	\$ 58.00	
50	BONNET RELEASE LEVER	1	\$ 14.00	
51	BONNET BOWDEN CABLE CAP	1	\$ 10.00	
52	HEADLIGHT MOUNTING - RH	1	\$ 118.00	<i>\$ 94.40</i>
53	LED HEADLIGHT - RH	1	\$ 5,589.00	<i>\$ 4,471.20</i>
54	HEADLIGHT ELECTRONIC POWER MODULE - RH	1	\$ 758.00	
55	HEADLIGHT HEAT SINK - RH	1	\$ 781.00	
56	LIFT CYLINDER - RH	`	\$ 210.00	
57	LIFTY CYLINDER HOSE - RH	1	\$ 80.00	<i>\$ 63.44</i>
58	LOCK CARRIER	1	\$ 1,272.00	<i>\$ 1,017.60</i>
59	RADIATOR COOLANT	6	\$ 266.00	<i>\$ 212.64</i>
60	RADIATOR AIR GUIDE - RH	1	\$ 38.00	<i>\$ 29.76</i>
SUB TOTAL SPARE PARTS		:	\$ 10,289.00	<i>\$ 13,637.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	13,637.52
61	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 84.00	\$	33.04
62	OUTSIDE TEMPERATURE SENSOR HOLDER	1	\$ 7.00		
63	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,072.00	\$	857.60
64	FRONT WINDOW SLOT SEAL - RH	1	\$ 224.00		
65	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
65a	Added parts - see attached		\$ 622.00	\$	497.60
66	SUNDRIES	1	\$ 400.00	\$	31.68
TOTAL SPARE PARTS		:	\$ 27,556.00	\$	15,117.44
TOTAL LABOUR CHARGES		:	\$ 15,144.00	\$	8,297.00
GRAND TOTAL		:	\$ 42,700.00	\$	23,414.44

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-01/12/21



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0920/2021/JT 23-Nov-21 GLORY 1 of 1 SDQ 3339 S AUDI Q3 SB 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Part</u> 1	COOLANT COMPRESSOR OIL - 250ML	\$ 622.00	\$ 497.60
GRAND TOTAL		\$ 622.00	\$ 497.60

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT