



Veron.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0920/2021/JT 23-Nov-21 GLORY 1 of 1 SDQ 3339 S AUDI Q3 SB 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Part</u> 1	COOLANT COMPRESSOR OIL - 250ML <i>Nec</i>	\$ 622.00	✓
GRAND TOTAL		\$ 622.00	

For Premium Automobiles Pte Ltd

Adrian Ling
22/11/21

Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408090
TEL: 636 2323 FAX: 6341 1183
EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1 S	1,335.00	✓
2	FRONT BUMPER CONNECTING PIECE ?	1 S	145.00	?
3	FRONT BUMPER FIXING PARTS <i>not new</i>	1 S	414.00	X
4	FRONT BUMPER CLOSING ELEMENT - RH ?	1 S	59.00	?
5	FRONT BUMPER TRIM - MANHATTAN GREY <i>int</i>	1 S	355.00	✓
6	FRONT BUMPER LOWER GRILLE - CENTER <i>int</i>	1 S	217.00	✓
7	FRONT PARKING AID SENSOR SUPPORT - LH/RH INNER <i>not new</i>	2 S	50.00	X
8	FRONT BUMPER LOWER GRILLE CAP ?	1 S	51.00	?
9	FRONT BUMPER CLOSING ELEMENT ?	1 S	190.00	?
10	FRONT BUMPER LOWER SPOILER <i>cracked</i>	1 S	760.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE - RH ?	1 S	153.00	?
12	FRONT BUMPER TRIM - RH MANHATTAN GREY ?	1 S	154.00	?
13	FRONT PARKING AID SENSOR BRACKET - RH ?	1 S	25.00	?
14	RADIATOR GRILLE <i>cracked</i>	1 S	1,928.00	✓
15	RADIATOR STRIKER PLATE <i>cracked</i>	1 S	244.00	✓
16	FRONT "360" DEGREE CAMERA CAP <i>not new</i>	1 S	56.00	X
17	FRONT "360" DEGREE CAMERA BRACKET	1 S	41.00	X
18	RADIATOR TOP COVER ?	1 S	244.00	?
19	FRONT "360" DEGREE CAMERA <i>new</i>	1 S	1,141.00	X
20	FRONT BUMPER FOAM FILLER PIECES ?	1 S	102.00	?
SUB TOTAL SPARE PARTS		:	\$ 7,678.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

Resurveyed.
Adrian G
22/11/21.
SP.S.

PREMIUM AUTOMOBILES




55 UBI ROAD 1 SINGAPORE 405699
 TEL 6366 2323 FAX 6341 1183
 EMAIL NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$ 916.00	✓
22	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 39.00	?
23	FRONT BUMPER TOP COVER <i>Cracked</i>	1	\$ 123.00	✓
24	* CAUTION * STICKER <i>None</i>	2	\$ 28.00	✓
25	AIR COND STICKER <i>None</i>	1	\$ 8.00	✓
26	FRONT PARKING AID SENSOR <i>Not ne</i>	3	TBC	x
27	FRONT PARKING AID SENSOR SEAL RING <i>Not ne</i>	4	\$ 9.00	x
28	FRONT BUMPER WIRING SET <i>Not ne</i>	1	\$ 572.00	x
29	SIGNAL HORN LOW TONE - RH <i>Not ne</i>	1	\$ 130.00	x
30	SIGNAL HORN BRACKET - RH ?	1	\$ 22.00	?
31	FRONT FENDER - RH <i>Repair</i>	1	\$ 1,286.00	x
32	FRONT FENDER ATTACHEMENT PARTS <i>Not ne</i>	1	\$ 63.00	x
33	FRONT FENDER BRACE - RH <i>Not ne</i>	1	\$ 88.00	x
34	FRONT FENDER BRACKET - RH <i>Not ne</i>	1	\$ 32.00	x
35	FRONT FENDER CLOSING ELEMENT - RH <i>Not ne</i>	1	\$ 33.00	x
36	FRONT WHEEL HOUSING LINER - RH <i>Not ne</i>	1	TBC	x
37	FRONT WHEEL HOUSING ATTACHEMENT PARTS <i>Not ne</i>	1	\$ 101.00	x
38	FRONT WHEEL HOUSING COVER - RH	1	\$ 16.00	x
39	BONNET <i>Dented</i>	1	\$ 3,508.00	✓
40	BONNET HINGES - LH / RH	2	\$ 146.00	?
SUB TOTAL SPARE PARTS		:	\$ 7,120.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES




15 UBI ROAD 1 SINGAPORE 408699
TEL 6366 2323 FAX 6341 1183
EMAIL HIRA KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET ATTACHEMENT PARTS ?	1	\$ 298.00	x
42	BONNET STRIKER - RH	1	\$ 110.00	x
43	BONNET SOUND ABSORBER	1	\$ 219.00	x
44	BONNET IMPACT PROTECTION - CENTER Not Cracked	1	\$ 28.00	✓
45	FRONT FENDER TOP COVER - RH Not m	1	\$ 41.00	x
46	PLENUM CHAMBER COVER Not m	1	\$ 129.00	x
47	BONNET BOWDEN CABLE - CENTER ? Not m	1	\$ 58.00	x
48	BONNET LID LOCK MICROSWITCH - RH	2	\$ 214.00	x
49	BONNET LATCH	1	\$ 58.00	x
50	BONNET RELEASE LEVER	1	\$ 14.00	x
51	BONNET BOWDEN CABLE CAP	1	\$ 10.00	x
52	HEADLIGHT MOUNTING - RH Cracked	1	\$ 118.00	✓
53	LED HEADLIGHT - RH Cracked	1	\$ 5,589.00	✓
54	HEADLIGHT ELECTRONIC POWER MODULE - RH Not m	1	\$ 758.00	x
55	HEADLIGHT HEAT SINK - RH Not m	1	\$ 781.00	x
56	LIFT CYLINDER - RH Not m	1	\$ 210.00	x
57	LIFT CYLINDER HOSE - RH Not m	1	\$ 80.00	x
58	LOCK CARRIER Cracked	1	\$ 1,272.00	✓
59	RADIATOR COOLANT Not m	6	\$ 266.00	✓
60	RADIATOR AIR GUIDE - RH Behind	1	\$ 38.00	✓
SUB TOTAL SPARE PARTS		:	\$ 10,289.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHAIZ@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 3339 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - UPPER LOWER <i>torn</i>	2 1	64.00	<i>42.</i>
62	OUTSIDE TEMPERATURE SENSOR HOLDER <i>None</i>	1	7.00	<i>x</i>
63	FRONT WHEEL ARCH COVER - LH / RH <i>None</i>	2	1,072.00	<i>✓</i>
64	FRONT WINDOW SLOT SEAL - RH <i>None</i>	1	224.00	<i>x</i>
65	FRONT NO PLATE <i>Deleted</i>	S/N	60.00	<i>✓</i>
66	SUNDRIES <i>?</i>	1	400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 26,934.00	
TOTAL LABOUR CHARGES		:	\$ 15,144.00	
GRAND TOTAL		:	\$ 42,078.00	

A/L CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.