

# Trust Autoworks

Blk 5035 #01-369 Ang Mo Kio Industrial Pk 2 Singapore 569538  
H/p 91082728

Fax: 64816131

Chan Kuan Ten  
Blk 124 Bedok North Road  
#07-139  
Singapore 460124

Vehicle No : SLU 868 K  
Make/Model : BMW 320i  
Year : 2009

*Not Available  
11 PM @ 4500h  
Running After Repair  
3 days*

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |  |            |           |            |   |
|-------|--|------------|-----------|------------|---|
| 1 pc  | Rear n/s tail-lamp - LED                     | 784        | Short     | \$850.00   | ✓ |
| 1 pc  | Rear end panel                               | repair     | R         | \$781.00   | X |
| 1 pc  | Rear end panel inner garnish                 | 1435       | R         | \$137.00   | X |
| 1 pc  | Rear bumper                                  | 755        | CPH/Bur   | \$1,550.00 | ✓ |
| 1 pc  | Rear bumper lower garnish                    | repair     | nn        | \$855.00   | ✓ |
| 1 pc  | Rear bumper reinforcement                    | photo      | R         | \$681.00   | X |
| 1 pc  | Rear bumper inner top bracket                | photo      | cm        | \$175.20   | ✓ |
| 1 pc  | Rear n/s bumper side bracket                 | photo      | ori       | \$195.00   | ✓ |
| 2 pcs | Rear reverse sensor                          | photo 0225 | Short     | \$285.00   | ✓ |
| 1 pc  | Rear exhaust silencer                        | photo 1150 | R         | \$570.00   | ✓ |
| 1 pc  | Front driver seat head rest collision sensor | 325 photo  | R         | \$1,875.00 | ✓ |
|       |  |            | nd        | \$385.00   | ✓ |
|       |  |            |           | \$8,054.20 |   |
|       |  |            | Less 10 % | \$805.42   |   |
|       |  |            |           | \$7,248.78 |   |

## Labour Charges

|  |          |            |
|--|----------|------------|
| Remove/renew the above accident parts including knocking, welding & cutting. | \$800.00 | 400        |
| To putty and spray paint   | \$800.00 | 400        |
| Check & reconnect wiring.  | \$45.00  | 20         |
| To respray anti-rust proofing treatment                                      | nn       | \$120.00 X |
| Remove/renew rear exhaust silencer.  | \$180.00 | 60         |
| Remove/refit rear boot upholstery to facilitate repair.                      | nn       | \$120.00 X |
| Diagnostic check on air bag system and to reset to factory specification     | nn       | \$450.00 X |
|  | Total    | \$9,763.78 |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: