

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIRim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 17/11 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / Fee: (\$ 3900)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:


Transportation:

) __ \$ + RS __ \$

) Photos

) Others

TOTAL



NTUC Ajax
door fitted sound proofing insulators-
16/11/14 1/5 @ 3900 confirmed with heavy 5 repair days
 (RED \$3438.56; 47%)

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Adhwaat
dan
17/11/24
d/s 3900 5-ly.

VEHICLE No: SJZ 475H

1PC	FRONT DOOR N/S	Body DO	\$792.40	✓
1PC	FRONT DOOR INNER LOCK N/S	Dryed	\$266.20	✓
1PC	FRONT DOOR INNER RUBBER N/S	ner	\$149.20	✓
1PC	REAR DOOR N/S	Body DO	\$736.20	✓
1PC	REAR DOOR GLASS OUTER MOULDING N/S	Self	\$86.50	✓
1PC	REAR DOOR GLASS REGULATOR & MOTOR N/S	Self / shell	\$366.20	✓
1PC	REAR DOOR GLASS INNER BRACKET N/S	Self	\$48.50	✓
1PC	REAR DOOR INNER TRIM BOARD N/S	De / To - 1	\$303.50	✓
1PC	REAR DOOR INNER RUBBER N/S	ner	\$148.20	✓
1PC	REAR DOOR INNER LOCK N/S	See	\$266.20	X
1PC	REAR DOOR HINGES @\$65.00	Turn	\$130.00	X
1PC	REAR DOOR CHECKER N/S	Turn	\$105.20	X
1PC	CENTRE PILLAR /S	ner	\$466.20	X
1PC	REAR FENDER N/S	ner	\$871.20	X
			\$7435.70	
			LESS 20%	\$3,788.56

S.NETT

1SET	FRONT DOOR INNER TRIM BOARD CLIPS N/S	ner	\$35.00	✓
1SET	FRONT DOOR INNER SOUND PROOF INSULATOR N/S	ner	\$450.00	300
1PC	FRONT DOOR VISOR N/S	ner	\$50.00	✓
1SET	REAR DOOR INNER TRIM BOARD CLIPS N/S	ner	\$35.00	✓
1PC	REAR DOOR VISOR N/S	ner	\$50.00	✓
1SET	N/S DOOR OUTER PROTECTOR	Turn	\$100.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$80.00	60
TO CONDUCT WHEEL ALIGNMENT	\$80.00	60
TO TRANSFER BOTH DOOR MECHANISM	\$120.00	✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	1000
TOTAL	\$7,338.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-30021
282
2601-68