

Date: 11/11/2021
Vehicle No: SNC6263L
Model: TOYOTA SIENNA HYBRID 1.5X CVT
Chassis: NHP1707178098-2019
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: GBG6362E
Date of Accident: 11/11/2021
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>na</i> \$40.00
2	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00
3	FRONT FENDER INNER SHIELD CLIPS	1		<i>na</i> \$40.00
4	FRONT DOOR INNER TRIM BOARD CLIPS	1		\$50.00
S/N TOTAL				\$180.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.	\$900.00	<i>500</i>
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH & ETC.	\$900.00	<i>680</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT CONTROL ARM RH & ETC.	\$250.00	<i>?</i>
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	<i>✓</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	<i>200</i>
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$100.00	<i>?</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	<i>800</i>
LABOUR TOTAL	\$2,430.00	

TING AN	TOTAL	\$10,701.75
---------	--------------	--------------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

