

Date: 11/11/2021
 Vehicle No: SNC6263L
 Model: TOYOTA SIENTA HYBRID 1.5X CVT
 Chassis: NHP1707178098-2019
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: GBG6362E
 Date of Accident: 11/11/2021
 Estimator: TING AN
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1		<i>nn</i> \$40.00
2	FRONT BUMPER CLIPS	1		<i>nn</i> \$50.00
3	FRONT FENDER INNER SHIELD CLIPS	1		<i>nn</i> \$40.00
4	FRONT DOOR INNER TRIM BOARD CLIPS	1		<i>nn</i> \$50.00
			S/N TOTAL	\$180.00

X
✓
✓
X

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$900.00 *500*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH & ETC. \$900.00 *680*

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT KNUCKLE ARM RH, FRONT WHEEL BEARING RH, FRONT CONTROL ARM RH & ETC. \$250.00 *200*

TO WHEEL ALIGNMENT & BALANCING. \$80.00 ✓

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *200*

TO DAIGNOSIS FAULT CODE & RESET MEMORY. *nn* \$100.00 X

TO TUFF KOTE & UNDERSEAL MATERIALS. \$120.00 *800*

LABOUR TOTAL \$2,430.00

TING AN TOTAL \$10,701.75

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

