

**GOLD PERFORMANCE PTE LTD**

Block 5033 Ang Mo Kio Industrial Park 2 #01-251/259

Singapore 569536

Mobile : 97289234

Email : goldperformancepl@gmail.com

UEN &amp; GST Registration no:202039762K

**11.11.2021****QUOTATION-THIRD PARTY CLAIM****Q:20211103****Pre-Repair Inspection / Survey**

Attention: The Claims Manager  
Auto & General Insurance (S) Pte Ltd  
190 Clemenceau Avenue #03-01  
Singapore Shopping Centre  
Singapore 239924

Email: claims@budgetdirect.com.sg

cc: Vehicle Owner - Tan Siew Hong

Dear Sir / Mdm

**ESTIMATE REPAIR COST OF SMG8863H (HONDA VESEL) on an accident on 06.11.2021  
at about 10.45am along 592-593 Sembawang Road (Outside of D'Rubinah Restaurant)**

Item	Description	Qty	Unit Price:S\$	Total:S\$
	<b><u>To supply parts:-</u></b>			
01	Rear Boots	1 pc	804.30	804.30
02	Rear Boots Lock	1 pc	256.10	256.10
03	Rear Boots Rubber	1 pc	101.30	101.30
04	Rear Windscreen Moulding	1 set	395.10	395.10
05	Rear Windscreen Gum	1 pc	44.00	44.00
06	Rear Boots "H" emblem	1 pc	38.00	38.00
07	Rear Boots "VESEL" emblem	1 pc	43.00	43.00
08	Rear TailLamp Assy	2 pcs	425.00	850.00
09	Rear Bumper	1 set	850.00	850.00
10	Rear Bumper Clips	6 pc	5.50	33.00
11	Rear Bumper Reflector	2 pcs	75.00	150.00
12	Rear Bumper Reverse Sensor 4pcs per set	1 set	301.70	301.70
13	Rear Panel	1 pcs	411.90	411.90
				<b>4,278.40</b>
	<b><u>To supply labour:-</u></b>			
01	To knock, weld, repair and renew all areas affected by the accident			700.00
02	To spray paint all areas affected by the accident			650.00
03	To remove and install rear windscreen			150.00
04	Loss of use - car rental days to be determined by surveyor	0 days	-	-
				<b>5,778.40</b>

We hope that our quotation will meet with your kind approval.  
Thank you.

Steven Ko

97289234