

CHINA TAIPING

Vehicle number	SMJ9809T
Make / Model	NISSAN NOTE
Chassis number	JN1TAAE12Z0982843
Accident date	10/11/21
Reference	2111-12

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	528.00/cut 480
2	REAR BUMPER RETAINER	121.00/nec
2	REAR BUMPER REFLECTOR	145.20/cut 1200/cra
2	REAR BUMPER REFLECTOR COVER	127.60/scr
1	REAR BUMPER BRACKET	106.26/nec
2	REAR BUMPER DAMPER	212.52/bt - 158.45
1	REAR BUMPER SPONGE	137.50/x
2	TAILLAMP	958.76/2an - 871.6
2	TAILLAMP BRACKET	121.00/x r
1	TAILGATE	1423.40/cut 108.2
1	TAILGATE EMBLEM - NOTE	103.40/nec 108.2
1	TAILGATE EMBLEM - LOGO	71.39/nec
1	TAILGATE OUTER GARNISH	320.10/nec 281.16
1	TAILGATE WEATHERSTRIP	126.50/? 108.46
1	TAILGATE LOCK	170.50/? DIS
1	TAILGATE LOCK STRIKER	60.50/DIS
1	TAILGATE INNER TRIM BOARD	217.80/? an
2	TAILGATE HINGE	165.00/? x R
1	TAILGATE GLASS MOULDING	102.00/nec
1	END PANEL	608.08/? BA - 552.8
1	END PANEL TOP GARNISH	119.30/? de
1	KEYLESS SENSOR	123.20/? an - 61.27
2	REAR FENDER INNER TRIM BOARD	872.08/? de - 756.8
1	SPARE TYRE TOP BOARD	477.07/? an - 263.7
1	SPARE TYRE COMPARTMENT	931.70/? an
1	EXHAUST SILENCER	646.80/? R
2	EXHAUST MOUNTING	38.00/? x
		9034.66
Less 20%		1806.93
		7227.73
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR BUMPER CLIP	30.00/nec
1 SET	TAILGATE INNER TRIM BOARD CLIP	30.00/nec
1 SET	REAR FENDER INNER TRIM CLIP	60.00/2 30
1 SET	REVERSE SENSOR	250.00/cut 200
1	REAR NUMBER PLATE	80.00/50
1	TAILGATE GLASS SEALANT	150.00/70
1	JOINT SEALANT	150.00/? 1.60
1	FLOOR INSULATOR	150.00/? 80

CHINA TAIPING

Vehicle number	SMJ9809T
Make / Model	NISSAN NOTE
Chassis number	JN1TAAE12Z0982843
Accident date	10/11/21
Reference	2111-12

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
2	TAILLAMP PANEL	475.20 PT 475.20
1	SPARE TYRE COMPARTMENT SPONGE	523.93 523.93 288
		999.13
	Less 20%	199.83
		799.30
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
1	REMOVE AND REFIT REAR SEAT TO FACILITATE REPAIR	250.00 120
	Subtotal	250.00
	Grand total	1049.30

CHINA TAIPING

Vehicle number	SMJ9809T
Make / Model	NISSAN NOTE
Chassis number	JN1TAAE12Z0982843
Accident date	10/11/21
Reference	2111-12

Qty	Particulars	Unit Price - SGD \$	
1	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		120
	REMOVE AND REFIT REAR SEAT TO FACILITATE REPAIR	250.00	
	Subtotal	250.00	
	Grand total	250.00	

[Signature]
 15/11/21

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	150.00 30
2	REMOVE AND REFIT REAR WINDSCREEN	200.00 120
3	REMOVE AND REFIT TRIMS AND GARNISH	150.00 400 30
4	REMOVE AND REPLACE EXHAUST SILENCER	150.00 1, NWX
5	REMOVE AND REFIT REVERSE SENSOR	150.00 30
6	REMOVE AND REFIT TAILGATE ATTACHMENTS	150.00 30
7	PANEL BEATING ON AFFECTED AREAS	1400.00 400 700 800
8	SPRAY PAINTING ON AFFECTED AREAS	1400.00 400 700 800
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		3900.00
Grand total		12027.73

Thwan@Lkhauto.com
 82235769
 12/11/21 1545
 4/5 after repair photo
 X3 days wp
 67.

6050 6300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: