

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%25	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	50k

TO: CHINA TAIPING

Vehicle No : YQ 4377 B

Make & Model : TOYOTA DYNA

DATE: 11/11/2021

ck

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	TAIL GATE ✓ BT	1	\$ 1,514.00	\$ 1,514.00	1370
2	TAIL GATE SIDE HANDLE / IPC	2	\$ 179.00	\$ 358.00	179
3	TAIL GATE SIDE LOCK / IPC BT	2	\$ 215.00	\$ 430.00	215
5	TAIL GATE LOWER SIDE RAILING RH	1	\$ 246.90	\$ 246.90	180
6	TAIL GATE LOWER SIDE RAILING MOUNTING	2	\$ 25.00	\$ 50.00	25
7	TAIL GATE HINGE X NN	4	\$ 124.10	\$ 496.40	
8	END PANEL X repair	1	\$ 564.20	\$ 564.20	
9	REAR FLOOR PANEL X NN	1	\$ 1,854.00	\$ 1,854.00	
11	TAIL LAMP / IPC CRA	2	\$ 354.90	\$ 709.80	208.5
12	TAIL LAMP BRACKET / IPC BT	2	\$ 172.40	\$ 344.80	97
13	TAIL LAMP REFELCTOR / IPC CRA	2	\$ 120.00	\$ 240.00	55.2
14	REAR CAR PLATE BRACKET / BT	1	\$ 233.00	\$ 233.00	184
15	REAR CAR PLATE LAMP X NN	2	\$ 60.00	\$ 120.00	
22	SIDE GATE RH X repair	1	\$ 1,898.60	\$ 1,898.60	
26	SIDE GATE BOTTOM PANEL RH X NN	1	\$ 752.40	\$ 752.40	
Subtotal :				\$ 9,812.10	2513.7
Less 25%				\$ 2,453.03	
Parts Total :				\$ 7,359.08	1885.27

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	TAIL GATE ALUMINIUM PLATE ✓ BT	1	\$ 1,500.00	\$ 1,500.00	300
2	TAIL GATE COMPANY STICKER	1	\$ 600.00	\$ 600.00	200
3	TAIL GATE STICKER(60km/h) /	1	\$ 40.00	\$ 40.00	15
4	TAIL GATE STICKER(13PAX) /	1	\$ 40.00	\$ 40.00	15
5	SIDE GATE COMPANY STICKER /	1	\$ 800.00	\$ 800.00	200

7 SIDE GATE ALUMINIUM PLATE ✓ <i>buy</i>	2	\$ 1,800.00	\$ 3,600.00	7 700
8 SIDE GATE ALUMINIUM PLATE RIVET <i>buy</i>	1	\$ 100.00	\$ 100.00	7 50
8 FLOOR PANEL ALUMINIUM PLATE <i>buy</i>	1	\$ 2,500.00	\$ 2,500.00	7 600
9 FLOOR PANEL ALUMINIUM PLATE RIVET <i>buy</i>	1	\$ 100.00	\$ 100.00	7 50
10 REAR CAR PLATE <i>cut</i>	1	\$ 60.00	\$ 60.00	10
11 REVERSE SENSOR (LONG) <i>rpm</i>	1	\$ 550.00	\$ 550.00	7 180
12 REVERSE SENSOR HOLDER <i>BT</i>	2	\$ 20.00	\$ 40.00	7 20
13 END PANEL SEALANT X <i>sum</i>	1	\$ 80.00	\$ 80.00	
14 FLOOR PANEL SEALANT X <i>sum</i>	1	\$ 80.00	\$ 80.00	
15 REAR COMPARTMENT CANOPY <i>(local repair)</i>	1	\$ 3,500.00	\$ 3,500.00	250
16 REAR BUMPER <i>BT</i>	1	\$ 1,400.00	\$ 1,400.00	150
17 REAR BUMPER BRACKET X <i>NN</i>	2	\$ 400.00	\$ 800.00	
SPECIAL NETT			\$ 15,790.00	

LABOUR (REAR)	PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,500.00	500
TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	700
TO PERFORM LIGHTING & WIRING CHECK	\$ 100.00	30
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	240
REMOVE AND INSTALL TAIL GATE, SIDE GATE	\$ 360.00	X <i>sum</i>
REMOVE AND RESEAL GATE RIVET SET	\$ 300.00	X <i>sum</i>
REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS.	\$ 100.00	40
REMOVE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 150.00	X <i>NN</i>
6035.27		
-20%: 4800		
LABOUR TOTAL	\$ 4,110.00	

Total Parts Cost	\$ 23,149.08
Total Labour Cost	\$ 4,110.00
Total Repair Cost	\$ 27,259.08

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

6 Days - 16/11/21
4/5
After repair photos
Gino Rip

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged: _____
 Signature: _____
 Date: _____