



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Auto & General Insurance
(Singapore) Pte Ltd
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Claim Details

Case Ref. No. : TP/112021/5074
Date : 12-11-2021
Accident Date : 10-11-2021

Vehicle Details

Make & Model : Honda CIVIC 1.6 VTI CVT
Chassis No : MRHFC5650GT000596
Registration No : SLJ3148T

Third Party Vehicle Details

Registration No : SKV615E

S/N	Description	Qty	Amount (\$)
1	FRONT LH HEADLAMP <i>cut</i>	1.00	\$668.50
2	FRONT BUMPER <i>cut</i>	1.00	\$579.90
3	FRONT BUMPER LH FOG LAMP COVER ?	1.00	\$30.60
4	FRONT BUMPER REINFORCEMENT ?	1.00	\$377.90
5	FRONT BUMPER LH SIDE RETAINER <i>re</i>	1.00	\$13.20
6	FRONT LH FENDER <i>re</i>	1.00	\$450.80
7	FRONT LH FENDER SIGNAL LIGHT <i>cut</i>	1.00	\$36.50
8	FRONT LH FENDER INNER SHIELD <i>re</i>	1.00	\$68.30
9	FRONT LH FENDER INNER SHIELD CLIPS @ \$4.20 <i>re</i>	10.00	\$42.00
10	FRONT LH WHEEL SPORT RIM <i>cut</i>	1.00	\$748.30
11	FRONT LH WHEEL KNUCKLE ARM ?	1.00	\$233.10
12	FRONT LH WHEEL KNUCKLE ARM BEARING ?	1.00	\$94.30
13	REAR BOOTLID <i>re</i>	1.00	\$554.90
14	REAR BOOTLID RH REFLECTOR <i>cut</i>	1.00	\$133.60
15	REAR BOOTLID LH REFLECTOR <i>cut</i>	1.00	\$133.60
16	REAR BOOTLID OUTER GARNISH <i>re</i>	1.00	\$114.80
17	REAR BOOTLID EMBLEM <i>re</i>	1.00	\$18.90
18	REAR BOOTLID "CIVIC" EMBLEM <i>re</i>	1.00	\$19.20
19	REAR BOOTLID "I-VTEC" EMBLEM <i>re</i>	1.00	\$22.50
20	REAR BOOTLID REVERSE CAMERA	1.00	\$406.40
21	REAR BOOTLID RH HINGE <i>cut</i>	1.00	\$58.90
22	REAR BOOTLID LH HINGE <i>cut</i>	1.00	\$58.90
23	REAR BOOTLID RH HINGE COVER <i>re</i>	1.00	\$17.50
24	REAR BOOTLID LH HINGE COVER <i>re</i>	1.00	\$17.50
25	REAR BOOTLID INNER TRIMBOARD <i>re</i>	1.00	\$42.10
26	REAR BOOTLID INNER LOCK <i>re</i>	1.00	\$155.80
27	REAR BOOTLID RUBBER <i>re</i>	1.00	\$160.10
28	REAR RH TAILLAMP <i>cut</i>	1.00	\$321.10
29	REAR LH TAILLAMP <i>cut</i>	1.00	\$321.10
30	REAR RH TAILLAMP PANEL <i>X repair</i>	1.00	\$152.10

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	REAR LH TAILLAMP PANEL / <i>buc</i>	1.00	\$152.10
32	REAR RH TAILLAMP LOWER BRACKET = <i>5 AR</i>	1.00	\$12.10
33	REAR LH TAILLAMP LOWER BRACKET	1.00	\$12.10
34	REAR BUMPER / <i>dis</i>	1.00	\$617.50
35	REAR BUMPER PARKING SENSOR @ \$155.40 <i>3 pcs - on</i>	4.00	\$621.60
36	REAR BUMPER PARKING SENSOR WIRE HARNESS ?	1.00	\$37.20
37	REAR BUMPER RH REFLECTOR X <i>NN</i>	1.00	\$17.10
38	REAR BUMPER RH REFLECTOR COVER = <i>5 at.</i>	1.00	\$19.30
39	REAR BUMPER LH REFLECTOR COVER	1.00	\$19.30
40	REAR BUMPER LH REFLECTOR X <i>NN</i>	1.00	\$17.10
41	REAR BUMPER RH SIDE RETAINER = <i>5 at</i>	1.00	\$35.10
42	REAR BUMPER LH SIDE RETAINER	1.00	\$35.10
43	REAR BUMPER REINFORCEMENT / <i>BT</i>	1.00	\$299.70
44	REAR BUMPER CLIPS @ \$4.20 / <i>MC</i>	10.00	\$42.00
45	REAR BUMPER UNDER COVER / <i>mis</i>	1.00	\$114.30
46	REAR END PANEL / <i>dis</i>	1.00	\$277.50
47	REAR END PANEL TOP TRIM / <i>re</i>	1.00	\$91.70
48	REAR SPARE TYRE PANEL / <i>dis (photo)</i>	1.00	\$336.40
49	REAR SPARE TYRE TOP COVER / <i>BT (photo)</i>	1.00	\$95.10
50	REAR EXHAUST SILENCER ?	1.00	\$742.50
51	REAR RH FENDER = <i>5 Buc</i>	1.00	\$812.30
52	REAR LH FENDER	1.00	\$812.30
53	REAR RH FENDER QUARTER GLASS = <i>5 buc</i>	1.00	\$227.10
54	REAR LH FENDER QUARTER GLASS	1.00	\$227.10
55	REAR RH FENDER INNER SHIELD = <i>5 TN</i>	1.00	\$82.10
56	REAR LH FENDER INNER SHIELD	1.00	\$82.10
57	REAR FENDER INNER SHIELD CLIPS @ \$4.20 / <i>MC</i>	20.00	\$84.00
58	REAR RH FENDER SIDE AIR VENT COVER ?	1.00	\$79.20
59	REAR LH FENDER SIDE AIR VENT COVER / <i>dis.</i>	1.00	\$79.20
60	REAR RH FENDER INNER TRIMBOARD = <i>5 clamp Crump</i>	1.00	\$199.30
61	REAR LH FENDER INNER TRIMBOARD	1.00	\$199.30
62	REAR LH FENDER INNER PANEL ?	1.00	\$392.50
63	REAR WINDSCREEN GLASS MOULDING / <i>MC N/C</i>	1.00	\$196.20
64	REAR LH FLOOR PANEL ?	1.00	\$655.90
65	REAR LH DOOR X <i>dis</i> / <i>Buc</i>	1.00	\$818.90
66	REAR LH DOOR INNER LOCK / <i>BT</i>	1.00	\$211.70
67	REAR PETROL TANK PIPE WITH TANK ?	1.00	\$759.60
68	REAR PETROL TANK PIPE COVER X <i>NN</i>	1.00	\$73.70
69	REAR SPEAKER PANEL ?	1.00	\$379.10
70	REAR LH SIDE MEMBER ?	1.00	\$1,217.50

Discount: -20%

\$17,236.30
(\$3,447.26)

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

71	FRONT LH WHEEL TYRE	X NN	1.00	\$13,789.04	
72	REAR SPARE TYRE PANEL INSULATOR	/ MC	1.00	\$280.00	
73	REAR NO. PLATE	/ Ant	1.00	\$250.00	
74	REAR WINDSCREEN GUM	/ MC.	1.00	\$40.00	
75	REAR RH FENDER QUARTER GLASS GUM	/ MC	1.00	\$60.00	
76	REAR LH FENDER QUARTER GLASS GUM	/ MC	1.00	\$60.00	
77	TO CHECK WHEEL ALIGNMENT		1.00	\$120.00	60
78	TO REMOVE AND REPLACE PETROL TANK		1.00	\$120.00	60
79	TO REMOVE AND REFIX FRONT UNDERCARRIAGE		1.00	\$280.00	?
80	TO REMOVE AND REFIX REAR UNDERCARRIAGE		1.00	\$280.00	200
81	TO REMOVE AND REFIX REAR SEAT CUSHION AND ROOF LINING		1.00	\$280.00	180
82	TO REMOVE AND REPLACE REAR LH FENDER QUARTER GLASS		1.00	\$100.00	50
83	TO REMOVE AND REPLACE REAR RH FENDER QUARTER GLASS		1.00	\$100.00	50
84	TO REPAIR DAMAGES		1.00	\$2,800.00	2400
85	TO SPRAY PAINTING		1.00	\$2,800.00	2400

Amusement sensor / DR.

Subtotal w/o GST:

\$21,419.04

16 Days

P/P

before paint photos

Gino Qianp

12/11/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: