

REPAIR ESTIMATE

DATE: 11-Nov-21
 MODEL: Hyundai Ioniq
 VEHICLE NO.: SHC3361C

INSURANCE: CHINA TAIPINGMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid Emblem-Hybrid	1		✓ \$24.30 <i>net</i>
	Boot Lid Emblem-Ioniq	1		✓ \$31.30 <i>net</i>
	Rear Bumper	1		✓ \$459.40 <i>del</i>
	Rear Bumper Side Bracket RH	1		\$55.80 <i>X nh</i>
	Rear Bumper Centre Moulding Assy	1	✓ 216.50	\$451.25 <i>net</i>
	Rear Bumper Cover Clips	10	\$2.20	✓ \$20.00 <i>net</i>
	Rear Bumper Reflector RH	1		\$41.45 <i>X nh</i>
	Boot Lid Lamp RH	1		\$794.40 <i>X nh</i>
	Taillamp RH	1		✓ \$870.40 <i>net</i>
	SUB TOTAL		1621.90	\$2,750.30
	LESS 20%			\$550.06
	DISCOUNTED TOTAL		1297.52	\$2,200.24
	Boot Lid ComfortDelGro	1		✓ \$35.00 <i>net</i>
	Boot Lid 65521111	1		✓ \$35.00 <i>net</i>
	Boot Lid APPS	1		✓ \$40.00 <i>net</i>
	Reverse Sensors	1	110	\$180.00 <i>X nh</i>
	S/NETT TOTAL			\$290.00
	SPARE PARTS TOTAL			\$2,490.24
	Labour Charge			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting Charge – Rear Fender RH		1335	\$900.00 <i>750</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	Check Lightings			\$40.00 <i>30</i>
	TOTAL LABOUR		2742.52	\$1,860.00
	ESTIMATE TOTAL		03days *	\$4,350.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taiping 97447747
WP' 11/11/21C 440 pm
#18 Missing before paint
Taiping @ Marston
02 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: