

ASS. REC. BY:

REF:

AIG/21011583/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

ays

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGW 2911D Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW 520i

c.c

1988

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

02599

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA12070BJ20786

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

275/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/11/21

D.O.I.

12/11/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/11 11:00 854506 Cont'd

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06483

Vehicle Insured : SMM9127L
Accident Date : 09-Nov-2021

Date : 11-Nov-2021

Our Ref : 021165 (AIG) / SHIJIE

PAGE : 1

CHEN ZHIMING JASON
BLK 497A TAMPINES STREET 45
#10-04
Singapore 520497

NOT Withheld
11 Nov 8 5450h
4 days

ESTIMATED COST OF REPAIR FOR BMW 520i SGW2911D

=====

1 pc	Bootlid	R	1,574.64	✓
1 pc	Bootlid "BMW" emblem	mu	110.81	✓
1 pc	Bootlid "520i" emblem	mu	87.48	✓
1 pc	Bootlid weatherstrip	su	285.77	X
1 pc	Bootlid lock	R	443.23	X
1 pc	Bootlid lock power drive	su	851.47	X
1 pc	Bootlid inner trim	su	443.23	X
1 pc	Rear bumper	Bu	1,283.04	✓ 1728.00
1 pc	Reverse sensors	mi	860.00	✓
1 pc	Rear bumper reflector (LH)	su	75.82	X
1 pc	Rear bumper reflector (RH)	su	75.82	X
1 pc	Rear bumper towing cover	su	59.40	X
1 pc	Rear bumper lower garnish	Bu	303.26	✓
1 pc	Rear bumper lower cover	su	64.80	X
1 pc	Rear bumper lower inner part	su	75.60	X
1 pc	Rear bumper inner part	CP	108.00	✓
1 pc	R bumper low garnish inner pt	su	81.00	X
1 pc	Rear bumper reinforcement	R	909.79	✓
1 pc	Rear bumper centre retainer	CP	128.30	✓
1 pc	Rear bumper side bracket (RH)	R	145.80	X
1 pc	Rear bumper side bracket (LH)	R	145.80	X
1 pc	Rear boot smart opener antenna	shot	116.64	✓
1 pc	Rear boot smart opener sensor	nd	145.00	✓
1 pc	Rear end panel	R	524.88	X
1 pc	Rear end panel top garnish	su	192.46	X
1 pc	Rr exhaust tail pipe chrome RH	su	174.96	X
1 pc	Rr exhaust tail pipe chrome LH	su	174.96	X
1 pc	Rear exhaust heatshield	R	93.31	✓

9,535.27

476.76

9,058.51

Con't Page 2 ...

LKK Auto Consultants hence notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMM9127L

Page : 2

1 pc Rear bumper clips
1 pc Rear number plate and case

Mr 60.00 sn ✓
Mr 60.00 sn X

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 500/

To putty and spray replaced parts

1,000.00 800/

To remove and renew reverse sensor
Wiring charges

50.00 ✓
60.00 20/

To apply undersealing

80.00 30/

Diagnose, program and reset smart
boot system

380.00 150/

Total : S\$11,548.51
=====

Singapore Dollars Eleven Thousand Five Hundred
and Forty Eight and Cents Fifty One Only

AKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date