

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI21007062/Evcn2-1	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	29/11/2021	
				Code:	CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PC 7915J	Veh. Inspected	d	SMX 9259G	
	Policy No.	DMB1SNW00001502102	Coverage (\$)		0.00	
	Claim No.	SNM21D203555/C02	Excess (\$)		0.00	
	Assign From	ADELINE CHNG	Assign Date		15/11/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	TOYOTA RAIZE	c.c		996	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	A200A0024263	Colour		WHITE	
	Odometer	12435 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R16	DUNLOP		5 mm	
	L/H Front Tyre	195/65 R16	DUNLOP		5 mm	
	R/H Rear Tyre	195/65 R16	DUNLOP		5 mm	
	L/H Rear Tyre	195/65 R16	DUNLOP		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/06/2021	Inspection Da	te	30/06/2021	
	Survey held at	WILLIAM LEE CAR AIR CON EN	IGINEERING			
		No.1 SOON LEE STREET #06-04 PIONEER CENTRE SINGAPORE 627605				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					