



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                            |                  |
|--|---|-----------------|----------------------------|------------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |   |                 | Ref: CS/AGI21011607/Gtf3n2 | Date: 05/05/2022 |
|  |   |                 | Code: AGI                  |                  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                            |                  |
| Insured Veh.   | SJS 441S  | Veh. Inspected  | SGW 2204L                  |                  |
| Policy No.   |   | Coverage (\$)   | 0.00                       |                  |
| Claim No.  | C10012455/CD  | Excess (\$)     | 0.00                       |                  |
| Assign From  | IVY RATILLA   | Assign Date     | 15/11/2021                 |                  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                            |                  |
| Make & Model   | HONDA CIVIC 1.6L  | c.c             | 1595                       |                  |
| Engine No.   | HIDDEN  | Year of Reg.    | 2007                       |                  |
| Chassis No.  | JHMF46207S200935  | Colour          | BLUE                       |                  |
| Odometer   | 189183 KM   | Steering        | IN ORDER                   |                  |
| Brakes   | IN ORDER  | Modification    | STANDARD ALLOY RIM         |                  |
| General  | GOOD  |                 |                            |                  |
| <b>3. Conditions of Tyres</b>  |   |                 |                            |                  |
|  | Size  | Make            | Balance                    |                  |
| R/H Front Tyre   | 205/55 R16  | YOKOHAMA        | 6 mm                       |                  |
| L/H Front Tyre   | 205/55 R16  | YOKOHAMA        | 6 mm                       |                  |
| R/H Rear Tyre  | 205/55 R16  | YOKOHAMA        | 6 mm                       |                  |
| L/H Rear Tyre  | 205/55 R16  | YOKOHAMA        | 6 mm                       |                  |
| <b>4. Description of Damages</b>   |   |                 |                            |                  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                 |                            |                  |
| <b>5. General Information</b>  |   |                 |                            |                  |
| Accident Date  | 12/11/2021  | Inspection Date | 16/11/2021                 |                  |
| Survey held at   | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                 |                            |                  |
| <b>5a. Remarks</b>   |   |                 |                            |                  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |   |                 |                            |                  |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                            |                  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | 6 Working Days             |                  |