## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Billy Tan Date: 18 Nov 2021 Attn:

# **Preliminary Advice**

Insured Vehicle No : SJD1451K

TP Vehicle No : SLB1149X Accident Date : 05/11/2021 : 15/11/2021 Make : MERCEDES-BENZ GLA200 Assignment Date

Est. Duration of Repair Date of Inspection : 16/11/21 :12

Inspection At : RICO 60 AUTO SERVICES PTE LTD

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	68,100.51
Revised Amount	:S\$	44,367.25
Check Items (Estimated)	:S\$	2,073.60
Total	:S\$	46,440.85

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: The above survey was conducted on a 'Without Prejudice' basis. ( X )

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.