



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 12.11.2021
Emailed : 20.12.2021, 4.40pm
Date survey : 15.11.2021

VEHICLE NO : SME 1172 A
MODEL : MIT ECLIPSE CROSS 1.5
WIP : 17414

Material	:	\$	4,573.03
Labour	:	\$	4,475.00
Sub-Total	:	\$	9,048.03
	:		-
Less Excess	:	\$	-
Total	:	\$	9,048.03
GST 7%	:	\$	633.36
Grand Total	:	\$	9,681.39
Finalise By/Date	:	LOI / 20/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 16/11/2021	<table> <tr> <td>Cust No/Name</td><td>/NG PECK SAI</td></tr> <tr> <td>Reg No/Reg Date</td><td>SME1172A / 19/09/2018</td></tr> <tr> <td>Date In/Mileage</td><td>13/11/2021/ 50306</td></tr> <tr> <td>Chassis/Package</td><td>JMAXTGK1WJZ003436 /DC17PT</td></tr> <tr> <td>Engine No</td><td>4B40DT6332</td></tr> <tr> <td>Make/Model</td><td>MIT/ECLIPSE CROSS 1.5 T/C SPORTS (T18)</td></tr> <tr> <td>Colour/Trim</td><td>U02 STERLING SILVER/ BK BLACK</td></tr> </table>	Cust No/Name	/NG PECK SAI	Reg No/Reg Date	SME1172A / 19/09/2018	Date In/Mileage	13/11/2021/ 50306	Chassis/Package	JMAXTGK1WJZ003436 /DC17PT	Engine No	4B40DT6332	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS (T18)	Colour/Trim	U02 STERLING SILVER/ BK BLACK
Cust No/Name	/NG PECK SAI														
Reg No/Reg Date	SME1172A / 19/09/2018														
Date In/Mileage	13/11/2021/ 50306														
Chassis/Package	JMAXTGK1WJZ003436 /DC17PT														
Engine No	4B40DT6332														
Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS (T18)														
Colour/Trim	U02 STERLING SILVER/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	17/12/2021/ 12:08	BLK	260 / AiTing	17414			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, RH FRONT FENDER, REPAIR RH FROTN FENDER INNER PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								1575.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, RH FRONT FENDER, RH FRONT FENDER INNER, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								1750.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR								80.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								40.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								40.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								120.00
M SUNDRY SUNDRIES								20.00
E PNT98000 RESPRAY LH FRONT FENDER & RH FRONT PILLAR → Supp.								700.00
X					1.00	1986.00	23.00	1529.22
X					1.00	506.00	23.00	389.62
X					1.00	81.00	23.00	62.37
X					1.00	718.00	23.00	552.86
X					1.00	382.00	23.00	294.14
X					1.00	17.00	23.00	13.09
X					1.00	77.00	23.00	59.29
X					1.00	214.00	23.00	164.78
X					1.00	18.00	23.00	13.86
X					1.00	787.00	23.00	605.99

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 16/11/2021	Cust No/Name	/NG PECK SAI
	Reg No/Reg Date	SME1172A / 19/09/2018
	Date In/Mileage	13/11/2021/ 50306
	Chassis/Package	JMAXTGK1WJZ003436 /DC17PT
	Engine No	4B40DT6332
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C SPORTS (T18)
	Colour/Trim	U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	17/12/2021/ 12:08	BLK	260 / AiTing	17414	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X	WEATHERSTRIP,HOOD		1.00	84.00	23.00	64.68
X	FENDER,FR RH		1.00	541.00	23.00	416.57
X	INSULATOR,FR FENDER,RH		1.00	52.00	23.00	40.04
X	SHIELD,FR WHEELHOUSE,RH		1.00	135.00	23.00	103.95
X	MOULDING,FR WHEEL ARCH,RH		1.00	151.00	23.00	116.27
X	COVER,FR DECK,RH		1.00	17.00	23.00	13.09
X	CLIP,RR BUMPER		10.00	3.00	23.00	23.10
X	CLIP,ENG ROOM COVER		10.00	2.00	23.00	15.40
X	GARNISH,FR PILLAR,RH		1.00	123.00	23.00	94.71
Z	TEXT					
	AIG OD CLAIM.					
	DOA : 12.11.21					
	SURVEYOR STEVE-LKK 15.11.21					
	POLICY NO : 1800111855-02 REPAIR 09 DAYS					

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,573.03	Nett	9,048.03
Labour	4,375.00	7% GST on	633.36
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	9,681.39
Sundry/Others	100.00		
Total(w/o GST)	9,048.03		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SME 1172 A**

<u>Materials</u>		<u>Cost (\$)</u>
1	Cover, Fr deck, RH	17.00 - m/s
2	Clips (x10)	30.00 - nec
3	Clips (x10)	20.00 - nec
4	Garnish, Fr pillar, RH	123.00 - BR

Total Materials		190.00
Less 23% discount		43.70

Total after discount		146.30

<u>Labour</u>		<u>Cost (\$)</u>
1	Respray LH front fender & Rh front pillar	700.00 ✓

Total labour		700.00
Total amount		846.30
7% GST		59.24

Grand total		<u>\$ 905.54</u>

Thank You.
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SME1172A

WIP: 17414

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Paint work on Frt LH fender \$350	? / SUPP			
2	SPY fty RH Piller \$350	? / SUPP			
3	CLIP - RR BUM (X10)	? / SUPP			MR 388150
4	CLIP - FRNG RO (X10)	? / SUPP			MYU488006
5		? / SUPP			24051684
6	COVER - FR DECK (RH)	? / SUPP			19/11/21
7	GR GARNISH - FR PILLAR - RH	? / SUPP			74051684
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Eclipse Cross

SURVEYOR: Steve-Luk

Work Order: R001585
License: SME1172A
Technician: 106 WENG SOON
Mileage: 50306
Date: 24.11.21 17:46

MITSUBISHI ECLIPSE CROSS 16" & 18" 2018-

Front : Left

Actual	Before	Specified Range
0°08'	0°06'	0°00' 0°30'
2°07'	2°07'	2°00' 3°00'
0°03'	-0°01'*	0°00' 0°06'
12°42'	12°44'	11°30' 14°30'
12°50'	12°50'	11°30' 15°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°03'	0°02'	0°00' 0°30'
2°49'	2°49'	2°00' 3°00'
0°04'	-0°04'*	0°00' 0°06'
14°00'	14°01'	11°30' 14°30'
14°03'	14°03'	11°30' 15°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°05'	0°04'	-0°45' 0°45'
-0°42'	-0°42'	-0°45' 0°45'
-1°19'*	-1°17'*	-0°45' 0°45'
0°07'	-0°05'*	0°01' 0°11'

Rear : Left

Actual	Before	Specified Range
-0°37'	-0°41'	-0°55' -0°25'
0°09'	0°02'*	0°06' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°45'	-0°48'	-0°55' -0°25'
0°08'	0°08'	0°06' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°07'	0°08'	-0°45' 0°45'
0°17'	0°10'*	0°11' 0°21'
0°01'	-0°03'	

Reg no. SDF 1172 A
to use PUF3x

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	GK1W 2018MY

you want to check all
the good
you know all the good
is done by QIC
is Test done check all Code

All DTCs

2021.11.24

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition				
	MPI/GDI/DIESEL	GAS_OC640000		No DTCs					
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs					
	4WS/Electric Power Steering	EPS_45840000		No DTCs					
	ABS/ASC/ASTC/WSS	ASC_42080014		No DTCs					
	SRS-AIR BAG	SRS_81047305		No DTCs					
	Air Conditioner	AC_80080017		No DTCs					
	ETACS	ETACS_83040800		No DTCs					
	TPMS (with KOS)	ETACS_83040800		No DTCs					
	Meter	METER_84088001		No DTCs					
	Steering Angle Sensor	GS_SAS_47000100_Fo rMUT3		No DTCs					
	AND	AND_8C080002		Non-target System					
	AUDIO (IntelligentDisplay)	AUDIO_8D080002		No DTCs					
	LIN	ETACS_83040800		Non-target System					
	KOS/OSS/IMMO/Keyless (with KOS)	ETACS_83040800		No DTCs					

All DTCs

2021.11.24

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition	
	CORNER SENSOR/SONAR	SONAR_9D080000		No DTCs			
	ACC/FCM	ACCSFCM_4B080004		Non-equipped System or Communication Error			
	Multi Around Monitor	CAMERA_94080100		No DTCs			
	EPB	EPB_4C080000		No DTCs			
	Gateway	GW_C1000000		Non-equipped System or Communication Error			
	FCM/LDW/AHB	ADAS_4B080003		No DTCs			
	BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error			
	BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error			
	HUD	HUD_9E080000		No DTCs			